



# CESCOM 10 - Aircraft Status Report

Owner: **JALAIR LP**

Aircraft Model: **501 - MODEL 501**

Aircraft Serial: **501-0169** Unit: **0566** Reg No: **C-GFEE**

Airworthiness: **31-Oct-1980**

Print Date: **22-Aug-2012 7:10PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>17995.4</b>	<b>22037</b>	<b>18-Aug-2012</b>	<b>.02</b>
<b>ENG 1</b>	<b>8791.4</b>	<b>9226</b>	<b>18-Aug-2012</b>	<b>.03</b>
<b>ENG 2</b>	<b>7046.1</b>	<b>6912</b>	<b>18-Aug-2012</b>	<b>.03</b>

## Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
051005L	INSPECT 91.411 ALTIMETER CAL	MTL			DAYS 22-Jul-2011 HRS 17954.1 LDG 22008		730		21-Jul-2013	10 m 29 d
5-12-01 051204	PHASE 1 INSPECTION	MTL			MTH 22-Jul-2011 HRS 17954.1 LDG 22008		24 300		31-Jul-2013	11 m 9 d 18254.1 258.7
5-12-02 051205	PHASE 2 INSPECTION	MTL			MTH 22-Jul-2011 HRS 17954.1 LDG 22008		24 300		31-Jul-2013	11 m 9 d 18254.1 258.7
5-12-03 051206	PHASE 3 INSPECTION	MTL			MTH 22-Jul-2011 HRS 17954.1 LDG 22008		24 300		31-Jul-2013	11 m 9 d 18254.1 258.7
5-12-04 051207	PHASE 4 INSPECTION	MTL			MTH 22-Jul-2011 HRS 17954.1 LDG 22008		24 300		31-Jul-2013	11 m 9 d 18254.1 258.7
5-12-05 051210	PHASE 5 INSPECTION	MTL			MTH 22-Jul-2011 HRS 17954.1 LDG 22008		36 1200		31-Jul-2014	23 m 9 d 19154.1 1158.7
5-12-0B 051218	PHASE B	MTL			MTH 22-Jul-2011 HRS 17954.1 LDG 22008		150		18104.1	108.7
5-12-10 051233	PHASE 10 INSPECTION	MTL			MTH 22-Jul-2011 HRS 17954.1 LDG 22008		100		18054.1	58.7
B243005	FUNCTIONAL CHECK BATTERY MARATHON NI-CAD BATTERY (CAPACITY CHECK): PHASE 10 INSPECTION	MTL		G6381E SN-UNKNOWN	MTH 22-Jul-2011 HRS 17954.1 LDG 22008					
B243007	FUNCTIONAL CHECK BATTERY SAFT NI-CAD BATTERY (CAPACITY CHECK): PHASE 10 INSPECTION	MTL		G6381E SN-UNKNOWN	MTH 22-Jul-2011 HRS 17954.1 LDG 22008					
5-12-12 051003	PHASE 12 INSPECTION				MTH 11-Apr-2006 HRS 17720 LDG 21747		600 600		18320 22347	324.6 310
5-12-13 051215	PHASE 13 INSPECTION	UNK			MTH 27-Jul-2012 HRS 17992.7 LDG 22033		3 100		31-Oct-2012 18092.7	2 m 9 d 97.3
5-12-15 052013 : B	PHASE 15 INSPECTION				MTH 31-May-2002 HRS 17404		1000		18404	408.6
5-12-16 052013 : C	PHASE 16 INSPECTION				MTH 28-Jun-2002 HRS 17439		3000		20439	2443.6
5-12-17 052013	PHASE 17 INSPECTION				MTH 15-Aug-1995 HRS 14446		10000		24446	6450.6
5-12-18 051005	PHASE 18 INSPECTION	UNK			MTH 08-Aug-2012 HRS 17992.7 LDG 22033		12		31-Aug-2013	12 m 9 d
5-12-20	PHASE 20 INSPECTION	MTL			MTH 22-Jul-2011 HRS 17954.1 LDG 22008		24			
B341001 COPILOT 051006I : R	CALIBRATION TEST ALTIMETER FAR 91.411: PHASE 20 INSPECTION	MTL		570-24929-013 1192	MTH 22-Jul-2011 HRS 17954.1 LDG 22008		24		22-Jul-2013	11 m 0 d



# CESCOM 10 - Aircraft Status Report

Owner: **JALAIR LP**  
 Aircraft Model: **501 - MODEL 501**  
 Aircraft Serial: **501-0169** Unit: **0566** Reg No: **C-GFEE**  
 Airworthiness: **31-Oct-1980**  
 Print Date: **22-Aug-2012 7:10PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>17995.4</b>	<b>22037</b>	<b>18-Aug-2012</b>	<b>.02</b>
<b>ENG 1</b>	<b>8791.4</b>	<b>9226</b>	<b>18-Aug-2012</b>	<b>.03</b>
<b>ENG 2</b>	<b>7046.1</b>	<b>6912</b>	<b>18-Aug-2012</b>	<b>.03</b>

## Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
B341001 NO. 1 <i>051007I</i>	CALIBRATION TEST AIR DATA COMPUTER	MTL		FAR 91.411: PHASE 20 INSPECTION 4013241-901 80051276	MTH 22-Jul-2011 HRS 17954.1 LDG 22008		24		22-Jul-2013	11 m 0 d
B341001 NO. 2	CALIBRATION TEST AIR DATA COMPUTER	MTL		FAR 91.411: PHASE 20 INSPECTION PN SN-UNKNOWN	MTH 22-Jul-2011 HRS 17954.1 LDG 22008		24		31-Jul-2013	11 m 9 d
B341001 STANDBY	CALIBRATION TEST ALTIMETER	MTL		FAR 91.411: PHASE 20 INSPECTION 24929-013 1192	MTH 22-Jul-2011 HRS 17954.1 LDG 22008		24		31-Jul-2013	11 m 9 d
B341001	CALIBRATION TEST ENCODING ALTIMETER	MTL		FAR 91.411: PHASE 20 INSPECTION 570-24929-013 1192	MTH 22-Jul-2011 HRS 17954.1 LDG 22008		24		31-Jul-2013	11 m 9 d
B341003 LEFT <i>051220I : L</i>	LEAK TEST STATIC SYSTEM	MTL		FAR 91.411 : PHASE 20 INSPECTION	MTH 22-Jul-2011 HRS 17954.1 LDG 22008		24		22-Jul-2013	11 m 0 d
B341003 RIGHT <i>051220I : R</i>	LEAK TEST STATIC SYSTEM	MTL		FAR 91.411 : PHASE 20 INSPECTION	MTH 22-Jul-2011 HRS 17954.1 LDG 22008		24		22-Jul-2013	11 m 0 d
B345001 NO. 1 <i>051221I</i>	CALIBRATION TEST ATC TRANSPONDER	MTL		FAR 91.413: PHASE 20 INSPECTION 622-1270-001 10678	MTH 22-Jul-2011 HRS 17954.1 LDG 22008		24		22-Jul-2013	11 m 0 d
B345001 NO. 2 <i>051221I : R</i>	CALIBRATION TEST ATC TRANSPONDER	MTL		FAR 91.413: PHASE 20 INSPECTION 622-1270-001 12375	MTH 22-Jul-2011 HRS 17954.1 LDG 22008		24		22-Jul-2013	11 m 0 d
5-12-22	PHASE 22 INSPECTION				MTH 31-Oct-1980		36			
B326003 <i>051227</i>	HYDROSTATIC TEST EMERGENCY GEAR AIR BOTTLE	UNK		: PHASE 22 INSPECTION 23111321 2033	MTH 08-Nov-2011		36		30-Nov-2014	27 m 8 d
5-12-23	PHASE 23 INSPECTION	UNK			MTH 08-Aug-2012 HRS 17992.7 LDG 22033		60			
B262002 AFT <i>121001 : A</i>	HYDROSTATIC TEST ENGINE FIRE EXTINGUISHER	UNK		: PHASE 23 INSPECTION 30401102 06993B2	MTH 08-Aug-2012 HRS 17992.7 LDG 22033		60		31-Aug-2017	60 m 9 d
B262002 FORWARD <i>121001 : F</i>	HYDROSTATIC TEST ENGINE FIRE EXTINGUISHER	UNK		: PHASE 23 INSPECTION 30401102 B6262	MTH 08-Aug-2012 HRS 17992.7 LDG 22033		60		31-Aug-2017	60 m 9 d
B350004 <i>051226 : C</i>	HYDROSTATIC TEST OXYGEN CYLINDER	UNK		: PHASE 23 INSPECTION 176176-64 4762-K906509	MTH 08-Aug-2012 HRS 17992.7 LDG 22033		60		31-Aug-2017	60 m 9 d
5-12-24 <i>052013 : A</i>	PHASE 24 INSPECTION				MTH 30-Jun-1997 HRS 15654		3000		18654	658.6
5-12-34	PHASE 34 INSPECTION	UNK			MTH 08-Aug-2012 HRS 17992.7 LDG 22033		6			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **JALAIR LP**  
 Aircraft Model: **501 - MODEL 501**  
 Aircraft Serial: **501-0169** Unit: **0566** Reg No: **C-GFEE**  
 Airworthiness: **31-Oct-1980**  
 Print Date: **22-Aug-2012 7:10PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>17995.4</b>	<b>22037</b>	<b>18-Aug-2012</b>	<b>.02</b>
<b>ENG 1</b>	<b>8791.4</b>	<b>9226</b>	<b>18-Aug-2012</b>	<b>.03</b>
<b>ENG 2</b>	<b>7046.1</b>	<b>6912</b>	<b>18-Aug-2012</b>	<b>.03</b>

### Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
A262003 CABIN <i>051018 : A</i>	WEIGHT CHECK PORTABLE EXTINGUISHER : PHASE 34 INSPECTION	UNK		C352 Y-23372	MTH 08-Aug-2012 HRS 17992.7 LDG 22033		6		28-Feb-2013	6 m 6 d
A262003 COCKPIT <i>051018 : F</i>	WEIGHT CHECK PORTABLE EXTINGUISHER : PHASE 34 INSPECTION	UNK		C352 Y-23332	MTH 08-Aug-2012 HRS 17992.7 LDG 22033		6		28-Feb-2013	6 m 6 d
5-12-37 <i>052010</i>	PHASE 37 INSPECTION				MTH 15-Aug-1995 HRS 14446		5000		19446	1450.6
5-12-40 <i>052013 : E</i>	PHASE 40 INSPECTION (NOT CURRENTLY USED)				MTH 15-Aug-1995 HRS 14446		A/R			
5-12-47	PHASE 47 INSPECTION	MTL			MTH 27-Sep-2011 HRS 17973.7 LDG 22008		144			
B262003 CABIN <i>051019 : A</i>	HYDROSTATIC TEST PORTABLE EXTINGUISHER : PHASE 47 INSPECTION	MTL		C352 Y-23372	MTH 29-Jun-2004		144		30-Jun-2016	46 m 8 d
B262003 COCKPIT <i>051019 : F</i>	HYDROSTATIC TEST PORTABLE EXTINGUISHER : PHASE 47 INSPECTION	MTL		C352 Y-23332	MTH 31-Aug-2000		144		31-Aug-2012	9 d
B262004 CABIN <i>051019B : A</i>	EMPTY/INSPECT/RECHARGE PORTABLE EXTINGUISHER : PHASE 48 INSPECTION	UVA		C352 Y-23372	MTH 22-Jul-2011		72		31-Jul-2017	59 m 9 d
B262004 COCKPIT <i>051019B : F</i>	EMPTY/INSPECT/RECHARGE PORTABLE EXTINGUISHER : PHASE 48 INSPECTION	UVA		C352 Y-23332	MTH 22-Jul-2011		72		31-Jul-2017	59 m 9 d
5-12-49 <i>051210 : SJ</i>	PHASE 49 INSPECTION	UNK			MTH 15-Jun-2010 HRS 17990.9		36 1200		30-Jun-2013 19190.9	10 m 8 d 1195.5
5-12-50 <i>052013 : F</i>	PHASE 50 INSPECTION	UNK			MTH 15-Jun-2010 HRS 17990.9		36 1200		30-Jun-2013 19190.9	10 m 8 d 1195.5
5-12-52 <i>051252</i>	PHASE 52 INSPECTION				MTH 11-Apr-2006 HRS 17720		2000		19720	1724.6
5-12-53 <i>051253</i>	PHASE 53 INSPECTION	UNK			MTH 24-Jul-2012 HRS 17992.7 LDG 22033		12		31-Jul-2013	11 m 9 d
5-12-MA <i>0512MA</i>	PHASE MA INSPECTION				MTH 11-Apr-2006 HRS 17720 LDG 21747		1000		22747	710
5-12-MD <i>0512MD</i>	PHASE MD INSPECTION				MTH 13-Jun-2000 HRS 16733 LDG 20795		5000		25795	3758
5-12-MF	PHASE MF INSPECTION				MTH 31-Oct-1980		N/A			
5-12-MG	PHASE MG INSPECTION				MTH 31-Oct-1980		N/A			
057110 E1	MINOR INSPECTION	MTL			MTH 22-Jul-2011 HRS 17954.1		24 300		31-Jul-2013 18254.1	11 m 9 d 258.7
057110 E2	MINOR INSPECTION	MTL			MTH 22-Jul-2011 HRS 17954.1		24 300		31-Jul-2013 18254.1	11 m 9 d 258.7
262037 AFT LEFT <i>262003 : AL</i>	REPLACE ENGINE FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE)			AE13083-5 SN-UNKNOWN	MTH 11-Apr-2006 HRS 17720		120		30-Apr-2016	44 m 8 d



# CESCOM 10 - Aircraft Status Report

Owner: **JALAIR LP**  
 Aircraft Model: **501 - MODEL 501**  
 Aircraft Serial: **501-0169** Unit: **0566** Reg No: **C-GFEE**  
 Airworthiness: **31-Oct-1980**  
 Print Date: **22-Aug-2012 7:10PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>17995.4</b>	<b>22037</b>	<b>18-Aug-2012</b>	<b>.02</b>
<b>ENG 1</b>	<b>8791.4</b>	<b>9226</b>	<b>18-Aug-2012</b>	<b>.03</b>
<b>ENG 2</b>	<b>7046.1</b>	<b>6912</b>	<b>18-Aug-2012</b>	<b>.03</b>

## Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
262038 AFT RIGHT 262003 : AR	REPLACE ENGINE FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE)			AE13083-5 SN-UNKNOWN	MTH 11-Apr-2006 HRS 17720		120		30-Apr-2016	44 m 8 d
262039 FORWARD LEFT 262003 : FL	REPLACE ENGINE FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE)			AE13083-5 SN-UNKNOWN	MTH 11-Apr-2006 HRS 17720		120		30-Apr-2016	44 m 8 d
262040 FORWARD RIGHT 262003 : FR	REPLACE ENGINE FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE)			AE13083-5 SN-UNKNOWN	MTH 11-Apr-2006 HRS 17720		120		30-Apr-2016	44 m 8 d
A324008 LEFT MAIN LANDING GEAR	INSPECT BRAKE ASSEMBLY (BRAKE ASSEMBLY GOODRICH P/N 2-1528-6 OR 2-1530-4 WITH SATOR DISKS PART NUMBER 133-893-2, THAT ARE IMPRESSION STAMPED "-" OR "A") AIRPLANES NOT EQUIPPED WITH THRUST:REVERSERS OR NOT USING THRUST REVERSERS:PHASE MF INSPECTION	UNK		5001446-6 S-MAR95-75	MTH 15-Jun-2010 HRS 17990.9		N/A			
A324008 RIGHT MAIN LANDING GEAR	INSPECT BRAKE ASSEMBLY (BRAKE ASSEMBLY GOODRICH P/N 2-1528-6 OR 2-1530-4 WITH SATOR DISKS PART NUMBER 133-893-2, THAT ARE IMPRESSION STAMPED "-" OR "A") AIRPLANES NOT EQUIPPED WITH THRUST REVERSERS OR NOT USING THRUST REVERSERS	UNK		5001446-6 JUL97-93	MTH 15-Jun-2010 HRS 17990.9		N/A			
A324009 LEFT MAIN LANDING GEAR	INSPECT BRAKE ASSEMBLY (BRAKE ASSEMBLY GOODRICH P/N 2-1528-6 OR 2-1530-4 WITH SATOR DISKS PART NUMBER 133-893-2, THAT ARE IMPRESSION STAMPED "-" OR "A") FOR AIRPLANES WITH AND USING THRUST REVERSERS. PHASE MG INSPECTION	UNK		5001446-6 S-MAR95-75	MTH 15-Jun-2010 HRS 17990.9		N/A			
A324009 RIGHT MAIN LANDING GEAR	INSPECT BRAKE ASSEMBLY (BRAKE ASSEMBLY GOODRICH P/N 2-1528-6 OR 2-1530-4 WITH SATOR DISKS PART NUMBER 133-893-2, THAT ARE IMPRESSION STAMPED "-" OR "A") FOR AIRPLANES WITH AND USING THRUST REVERSERS	UNK		5001446-6 JUL97-93	MTH 15-Jun-2010 HRS 17990.9		N/A			
710010 E1	OVERHAUL				MTH 30-Jun-1997 HRS 15654		3500		19154	1158.6
710010 E2	OVERHAUL				MTH 13-Jul-2011 HRS 17953.5 LDG 21983		3500	3336.3	18117.2	121.8
710020 E1	HOT SECTION INSPECTION				MTH 31-May-2002 HRS 17402	-250	1800		18952	956.6
710020 E2	HOT SECTION INSPECTION				MTH 13-Jul-2011 HRS 17953.5 LDG 21983		1800	3336.3	17953.5	-41.9
720010 E1	OIL ANALYSIS						A/R			Over Due
725040 E1	REPLACE HIGH TURBINE BLADES				MTH 30-Jun-1997 HRS 15654		3500		19154	1158.6
725040 E2	REPLACE HIGH TURBINE BLADES				MTH 13-Jul-2011 HRS 17953.5 LDG 21983		3500	3336.3	18117.2	121.8
731025 E1	VISUALLY INSPECT FUEL-OIL COOLER				HRS 9204		A/R		19154	1158.6
731035 E1	VISUALLY INSPECT MOTIVE FLOW VALVE				HRS 9204		1800		19154	1158.6
731090 E1	VISUALLY INSPECT FLOW DIVIDER VALVE				HRS 9204		1800		19154	1158.6
741030 E1 LOWER	VISUALLY INSPECT IGNITION EXCITER	MTL		10-381550-22 NN01446608	MTH 22-Jul-2011 HRS 17954.1		24 300		31-Jul-2013 18254.1	11 m 9 d 258.7

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **JALAIR LP**  
 Aircraft Model: **501 - MODEL 501**  
 Aircraft Serial: **501-0169** Unit: **0566** Reg No: **C-GFEE**  
 Airworthiness: **31-Oct-1980**  
 Print Date: **22-Aug-2012 7:10PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>17995.4</b>	<b>22037</b>	<b>18-Aug-2012</b>	<b>.02</b>
<b>ENG 1</b>	<b>8791.4</b>	<b>9226</b>	<b>18-Aug-2012</b>	<b>.03</b>
<b>ENG 2</b>	<b>7046.1</b>	<b>6912</b>	<b>18-Aug-2012</b>	<b>.03</b>

## Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
741030 E1 UPPER	VISUALLY INSPECT IGNITION EXCITER	MTL			MTH 22-Jul-2011 HRS 17954.1		24 300		31-Jul-2013 18254.1	11 m 9 d 258.7
741030 E2 LOWER	VISUALLY INSPECT IGNITION EXCITER	MTL		10-381550-2A SN-UNKNOWN	MTH 22-Jul-2011 HRS 17954.1		24 300			
741030 E2 UPPER	VISUALLY INSPECT IGNITION EXCITER	MTL		PN SN-UNKNOWN	MTH 22-Jul-2011 HRS 17954.1		24 300			
792010 E1	CHANGE OIL	YHU			MTH 20-May-2009 HRS 17904		O/C			
792010 E2	CHANGE OIL	UVA			MTH 21-Jul-2011 HRS 17953.5 LDG 21983		O/C			
792020 E2	INSPECT/CLEAN OR REPLACE OIL FILTER ELEMENT	UVA		3015330 SN-UNKNOWN	MTH 21-Jul-2011 HRS 17953.5 LDG 21983		200		18153.5	158.1



## CESCOM 10 - Aircraft Status Report

Owner: **JALAIR LP**  
 Aircraft Model: **501 - MODEL 501**  
 Aircraft Serial: **501-0169** Unit: **0566** Reg No: **C-GFEE**  
 Airworthiness: **31-Oct-1980**  
 Print Date: **22-Aug-2012 7:10PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>17995.4</b>	<b>22037</b>	<b>18-Aug-2012</b>	<b>.02</b>
<b>ENG 1</b>	<b>8791.4</b>	<b>9226</b>	<b>18-Aug-2012</b>	<b>.03</b>
<b>ENG 2</b>	<b>7046.1</b>	<b>6912</b>	<b>18-Aug-2012</b>	<b>.03</b>

### Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
211002	EMERGENCY PRESSURIZATION VALVE	*CF		224465-2 713	MTH 31-Oct-1980		O/C			
212002 CABIN	AFT OVERHEAD BLOWER 9912323-2			BC61A901-2 646A	MTH 07-Jul-2005 HRS 17700		1200	0	18900	904.6
212003	AIR INLET DOOR ACTUATOR	*CF		1H56-1 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
212005 LEFT CABIN	COOLING FAN	*CF		WS2107F30 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
212005 RIGHT CABIN	COOLING FAN	*CF		WS2107F30 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
212010	DOOR ACTUATOR MOTOR ASSEMBLY 9910059-3	*CF		5A3032 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
213001 CABIN	PRESSURE INDICATOR 3001J14	*CF		C668511-0102 15470	MTH 31-Oct-1980		O/C			
213002	PRESSURIZATION CONTROLLER			130356-5 19651	MTH 17-Jun-1990 HRS 10534		O/C	0		
213003 CABIN	RATE OF CLIMB INDICATOR 35060-1128	*CF		C668513-0101 W836G	MTH 31-Oct-1980		O/C			
213005 LEFT CABIN	ALTITUDE LIMIT VALVE 9912055-1	*CF		102466-1 102916	MTH 31-Oct-1980		O/C			
213005 RIGHT CABIN	ALTITUDE LIMIT VALVE 9912055-1	*CF		102466-1 292873	MTH 31-Oct-1980		O/C			
213006	SAFETY OUTFLOW VALVE	*CF		103576-13 10-686	MTH 31-Oct-1980		O/C			
213007	NORMAL OUTFLOW VALVE	*CF		103576-12 129739	MTH 31-Oct-1980		O/C			
213008	MANUAL DUMP VALVE	*CF		2101701-1 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
213009 LEFT	BLEED AIR FLOW CONTROL VALVE YSC			5063-00-1 0046	MTH 10-Aug-2004 HRS 17657		O/C	0		
213009 RIGHT	BLEED AIR FLOW CONTROL VALVE			5063-00-1 0071	MTH 26-Apr-2004 HRS 17626		O/C	0		
213013	PNEUMATIC RELAY	*CF		130358-1 19-707	MTH 31-Oct-1980		O/C			
215001	REFRIGERATION UNIT 9912069-21	*CF		738443-13 51542	MTH 31-Oct-1980		O/C			
215002	ASPIRATOR AND FAN HOUSING	*CF		740730-2 SN-UNKNOWN	MTH 31-Oct-1980		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **JALAIR LP**  
 Aircraft Model: **501 - MODEL 501**  
 Aircraft Serial: **501-0169** Unit: **0566** Reg No: **C-GFEE**  
 Airworthiness: **31-Oct-1980**  
 Print Date: **22-Aug-2012 7:10PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>17995.4</b>	<b>22037</b>	<b>18-Aug-2012</b>	<b>.02</b>
<b>ENG 1</b>	<b>8791.4</b>	<b>9226</b>	<b>18-Aug-2012</b>	<b>.03</b>
<b>ENG 2</b>	<b>7046.1</b>	<b>6912</b>	<b>18-Aug-2012</b>	<b>.03</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
215004	AIR CYCLE MACHINE			738384-10 3698	MTH 17-Aug-1994 HRS 13745		5000	0	18745	749.6
RECOMMENDED ECONOMIC OVERHAUL PERIOD DEFINED BY HAMILTON STANDARD.										
215005	BYPASS VALVE 9912069-1	YTS		738385-4 130661	MTH 07-Dec-1982 HRS 1546		O/C	0		
215006	OVERHEAT SWITCH	*CF		746833-1 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
215007	GROUND OPERATION VALVE 9912068-3	*CF		225655 234	MTH 31-Oct-1980		O/C			
216001	CABIN TEMPERATURE SELECTOR	*CF		5518118-3 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
216002	TEMPERATURE CONTROL UNIT 9912069-22	*CF		754661-5 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
216003	DUCT TEMPERATURE SENSOR 9912069-14			754691-1 87045059	MTH 18-Aug-1988 HRS 9012		O/C	0		
216004	CABIN TEMPERATURE SENSOR 9912069-15	*CF		754681-1 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
216005	CENTRIFUGAL BLOWER 9912070-1	YTS		19A2338 141	MTH 08-Feb-1984 HRS 3307		O/C	0		
216006	CABIN TEMPERATURE INDICATOR	*CF		0221-003 28130	MTH 31-Oct-1980		O/C			
221008	AUTOPILOT COMPUTER SP-200			4008519-911 80011377	MTH 20-Jan-1994 HRS 13250		O/C	9403		
221009	AUTOPILOT CONTROLLER PC-500			4018639-901 79013735	MTH 07-Jun-1991 HRS 11146		O/C	0		
221010 AILERON	SERVO ACTUATOR SM-200	*CF		4006719-904 055307	MTH 31-Oct-1980		O/C			
221010 ELEVATOR	SERVO ACTUATOR SM-200	*CF		4006719-904 055310	MTH 31-Oct-1980		O/C			
221010 RUDDER	SERVO ACTUATOR SM-200	*CF		4006719-906 614687	MTH 31-Oct-1980		O/C			
232002 NO. 2	VHF COMMUNICATION ANTENNA 9912084-1	*CF		VF10-108-1 744	MTH 31-Oct-1980		O/C			
232003 NO. 1	VHF COMMUNICATION ANTENNA			VFS10-90-5 1738	MTH 21-Sep-1989 HRS 9853		O/C	0		
232010 NO. 1	TOP COMMUNICATION TRANSCEIVER VHF-20A			622-1879-002 16162	MTH 10-Oct-1989 HRS 9913		O/C	755		



## CESCOM 10 - Aircraft Status Report

Owner: **JALAIR LP**  
 Aircraft Model: **501 - MODEL 501**  
 Aircraft Serial: **501-0169** Unit: **0566** Reg No: **C-GFEE**  
 Airworthiness: **31-Oct-1980**  
 Print Date: **22-Aug-2012 7:10PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>17995.4</b>	<b>22037</b>	<b>18-Aug-2012</b>	<b>.02</b>
<b>ENG 1</b>	<b>8791.4</b>	<b>9226</b>	<b>18-Aug-2012</b>	<b>.03</b>
<b>ENG 2</b>	<b>7046.1</b>	<b>6912</b>	<b>18-Aug-2012</b>	<b>.03</b>

### Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
232010 NO. 2	BOTTOM COMMUNICATION TRANSCEIVER VHF-20A			622-1879-002 7522	MTH 10-Oct-1989 HRS 9913		O/C	99		
232011	COMMUNICATION CONTROL	*CF		1U434-001 243	MTH 31-Oct-1980		O/C			
235001 LEFT	AUDIO AMPLIFIER			1640-1 257	MTH 25-Nov-1998 HRS 16133		O/C	9615		
235001 RIGHT	AUDIO AMPLIFIER			1660-1 257	MTH 18-May-1998 HRS 15889		O/C	3		
235003 CABIN	SPEAKERS	*CF		48FU2103 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
235003 COCKPIT	SPEAKERS	*CF		48FU2103 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
235006 LEFT	TELEX HEADSET	*CF		62629-00 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
235006 RIGHT	TELEX HEADSET	*CF		62629-00 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
237001	COCKPIT VOICE RECORDER			A100 4593	MTH 07-Jul-1997 HRS 15656		O/C	2		
242001 NO. 1	AC INVERTER			PC17-3 153	MTH 14-Sep-1984 HRS 4291		O/C	0		
242001 NO. 2	AC INVERTER			PC17-3 2212	MTH 04-Apr-1985 HRS 5101		O/C	0		
242002	AC FAIL MONITOR	*CF		1371-1 683	MTH 31-Oct-1980		O/C			
243001 NO. 1	ENGINE STARTER/GENERATOR 9912038-3			23076-001-1 329	MTH 09-May-2008 HRS 17851		1000	0	18851	855.6
243001 NO. 2	ENGINE STARTER/GENERATOR 9912038-4			23080-001-1 2941	MTH 11-Apr-2006 HRS 17720		1000	0	18720	724.6
243003 LEFT	GENERATOR CONTROL UNIT 9912039-3			51509-006BR 6255	MTH 25-Nov-1998 HRS 16133		O/C	1043		
243003 RIGHT	GENERATOR CONTROL UNIT 9912039-3			51509-006BR 11115A	MTH 25-Nov-1998 HRS 16133		O/C	146		
243004 LEFT	AMMETER			C662501-0102 57	MTH 05-Nov-1985 HRS 5992		O/C	0		
243004 RIGHT	AMMETER	*CF		C662501-0102 3014	MTH 31-Oct-1980		O/C			
243005	VOLTMETER 153LV30	*CF		C662502-0101 895	MTH 31-Oct-1980		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.





# CESCOM 10 - Aircraft Status Report

Owner: **JALAIR LP**  
 Aircraft Model: **501 - MODEL 501**  
 Aircraft Serial: **501-0169** Unit: **0566** Reg No: **C-GFEE**  
 Airworthiness: **31-Oct-1980**  
 Print Date: **22-Aug-2012 7:10PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>17995.4</b>	<b>22037</b>	<b>18-Aug-2012</b>	<b>.02</b>
<b>ENG 1</b>	<b>8791.4</b>	<b>9226</b>	<b>18-Aug-2012</b>	<b>.03</b>
<b>ENG 2</b>	<b>7046.1</b>	<b>6912</b>	<b>18-Aug-2012</b>	<b>.03</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
243007	BATTERY -			G6381E SN-UNKNOWN	MTH 19-Dec-2002 HRS 17594		O/C	0		
243008	BATTERY TEMPERATURE MODULE *CF			1529-1 606	MTH 31-Oct-1980		O/C			
243009	BATTERY TEMPERATURE GAUGE			1229-1 1126	MTH 05-Jul-1988 HRS 8912		O/C	21		
243010 G	GAGE TEMP SENSOR -- YTS			1166-1 3908	MTH 06-Mar-1983 HRS 1908		O/C	0		
243010	BATTERY TEMPERATURE SENSOR			1166-1 5357	MTH 26-Sep-1986 HRS 6904		O/C	0		
243011	CURRENT / VOLT CONTROLLER			1301-1 149A	MTH 30-Sep-1988 HRS 9081		O/C	0		
243012	CURRENT SENSOR ICT			1302-1 748A	MTH 04-Dec-1981 HRS 354		O/C	0		
244001 K11	400 AMP RELAY *CF			AN3380-1 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
244001 K12	400 AMP RELAY *CF			AN3380-1 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
244001 K13	400 AMP RELAY *CF			AN3380-1 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
244001 K1	400 AMP RELAY *CF			AN3380-1 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
244001 K7	400 AMP RELAY *CF			AN3380-1 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
244001 K8	400 AMP RELAY *CF			AN3380-1 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
245001 CENTER	5 VOLT LIGHT DIMMER			1505-1 2637	MTH 02-Nov-1992 HRS 12373		O/C	6515		
245001 LEFT	5 VOLT LIGHT DIMMER YTS			1505-1 2202	MTH 20-Jul-1983 HRS 2496		O/C	1506		
245001 RIGHT	5 VOLT LIGHT DIMMER			1505-1 1066	MTH 01-Dec-1992 HRS 12464		O/C	0		
251001 LEFT	INERTIA REEL *CF			CM4033 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
251001 RIGHT	INERTIA REEL *CF			CM4033 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
256009 344009	EMERGENCY LOCATER TRANSMITTER ANTENNA SWF			DMQ18-1A SN-UNKNOWN	MTH 10-Aug-1989 HRS 9678		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **JALAIR LP**  
 Aircraft Model: **501 - MODEL 501**  
 Aircraft Serial: **501-0169** Unit: **0566** Reg No: **C-GFEE**  
 Airworthiness: **31-Oct-1980**  
 Print Date: **22-Aug-2012 7:10PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>17995.4</b>	<b>22037</b>	<b>18-Aug-2012</b>	<b>.02</b>
<b>ENG 1</b>	<b>8791.4</b>	<b>9226</b>	<b>18-Aug-2012</b>	<b>.03</b>
<b>ENG 2</b>	<b>7046.1</b>	<b>6912</b>	<b>18-Aug-2012</b>	<b>.03</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
256019 344008	EMERGENCY LOCATER TRANSMITTER	UNK		453-5012-(366) 15619	MTH 08-Aug-2012 HRS 17992.7 LDG 22033		O/C			
256025 344010	EMERGENCY LOCATER TRANSMITTER BATTERY	UNK		452-0222 353876-022	MTH 08-Aug-2012 HRS 17992.7 LDG 22033		36	0	31-Aug-2015	36 m 9 d
261001 NO. 1 ENGINE	FIRE DETECTION SENSOR 9912036-3			244-18882 SN-UNKNOWN	MTH 23-Feb-1988 HRS 8484		O/C	0		
261001 NO. 2 ENGINE	FIRE DETECTION SENSOR 9912036-3	*CF		244-18882 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
261002 NO. 1 ENGINE	FIRE DETECTION CONTROL 9912036-2			377-02808 8513-006	MTH 07-Feb-1986 HRS 6232		O/C	0		
261002 NO. 2 ENGINE	FIRE DETECTION CONTROL 9912036-2	YTS		377-02808 80H004	MTH 20-Dec-1983 HRS 3105		O/C	3323		
262001 AFT	ENGINE FIRE EXTINGUISHER 9912048-2			30401102 06993B2	MTH 05-Jul-2007 HRS 17787		O/C	132		
262001 FORWARD	ENGINE FIRE EXTINGUISHER 9912048-2			30401102 B6262	MTH 05-Jul-2007 HRS 17787		O/C	163		
262002 CABIN	PORTABLE EXTINGUISHER UVA			C352 Y-23372	MTH 07-Jul-2011 HRS 17953.5 LDG 21983		O/C	0		
262002 COCKPIT	PORTABLE EXTINGUISHER UVA			C352 Y-23332	MTH 07-Jul-2011 HRS 17953.5 LDG 21983		O/C	0		
262003 AFT LEFT	ENGINE FIRE EXTINGUISHER CARTRIDGE			AE13083-5 SN-UNKNOWN	MTH 11-Apr-2006 HRS 17720		120	0	30-Apr-2014	20 m 8 d
262003 AFT RIGHT	ENGINE FIRE EXTINGUISHER CARTRIDGE			AE13083-5 SN-UNKNOWN	MTH 11-Apr-2006 HRS 17720		120	0	30-Apr-2014	20 m 8 d
262003 FORWARD LEFT	ENGINE FIRE EXTINGUISHER CARTRIDGE			AE13083-5 SN-UNKNOWN	MTH 11-Apr-2006 HRS 17720		120	0	30-Apr-2014	20 m 8 d
262003 FORWARD RIGHT	ENGINE FIRE EXTINGUISHER CARTRIDGE			AE13083-5 SN-UNKNOWN	MTH 11-Apr-2006 HRS 17720		120	0	30-Apr-2014	20 m 8 d
271001	AILERON TRIM TAB ACTUATOR *CF			5565450-51 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
272001	RUDDER TRIM TAB ACTUATOR *CF			5565450-53 379-53	MTH 31-Oct-1980		O/C			
273002	ELEVATOR TRIM ELECTRICAL ACTUATOR			5115231-30 PAL30	MTH 28-Jun-1994 HRS 13525		O/C	0		
273003	ELEVATOR TRIM TAB ACTUATOR			5565450-80 R05354	MTH 28-Jun-1994 HRS 13525		O/C	0		
275001 LEFT	FLAP MOTOR 9910055-3			FS30-3 332	MTH 17-Sep-1998 HRS 16050		O/C	3307		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **JALAIR LP**  
 Aircraft Model: **501 - MODEL 501**  
 Aircraft Serial: **501-0169** Unit: **0566** Reg No: **C-GFEE**  
 Airworthiness: **31-Oct-1980**  
 Print Date: **22-Aug-2012 7:10PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>17995.4</b>	<b>22037</b>	<b>18-Aug-2012</b>	<b>.02</b>
<b>ENG 1</b>	<b>8791.4</b>	<b>9226</b>	<b>18-Aug-2012</b>	<b>.03</b>
<b>ENG 2</b>	<b>7046.1</b>	<b>6912</b>	<b>18-Aug-2012</b>	<b>.03</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
275001 RIGHT	FLAP MOTOR 9910055-4			FS30-5 1824	MTH 26-Jun-1986 HRS 6703		O/C	0		
275002 LEFT	FLAP GEARBOX			5565175-38 20698-1	MTH 17-Sep-1998 HRS 16050		3000	0	19050	1054.6
275002 RIGHT	FLAP GEARBOX			5565175-38 2481	MTH 17-Sep-1998 HRS 16050		3000	0	19050	1054.6
276001 LEFT	SPEED BRAKE ACTUATOR			5527230-1 S110781	MTH 14-Mar-1989 HRS 9395		O/C	0		
276001 RIGHT	SPEED BRAKE ACTUATOR			5527230-1 110091	MTH 26-Jan-1992 HRS 11760		O/C	0		
281002 LEFT AFT	FUEL DRAIN VALVE 9912083-1	*CF		6904-079 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
281002 LEFT FORWARD	FUEL DRAIN VALVE 9912083-1	*CF		6904-079 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
281002 LEFT MID	FUEL DRAIN VALVE 9912083-1	*CF		6904-079 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
281002 RIGHT AFT	FUEL DRAIN VALVE 9912083-1	*CF		6904-079 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
281002 RIGHT FORWARD	FUEL DRAIN VALVE 9912083-1	*CF		6904-079 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
281002 RIGHT MID	FUEL DRAIN VALVE 9912083-1	*CF		6904-079 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
282001 LEFT	FUEL BOOST PUMP 9912017-2			1C7-12 8AP104	MTH 13-Nov-1998 HRS 16113		O/C	0		
282001 RIGHT	FUEL BOOST PUMP 9912017-2	*CF		1C7-12 2F101	MTH 31-Oct-1980		O/C			
282002 LEFT	MOTIVE FLOW PRESSURE RATIO SWITCH 9912082-2	TOL		1106P56 2169	MTH 13-Nov-1981 HRS 345		O/C	0		
282002 RIGHT	MOTIVE FLOW PRESSURE RATIO SWITCH 9912082-2	YTS		1106P56 2021	MTH 30-Dec-1982 HRS 1666		O/C	0		
284001 LEFT	LOW FUEL LEVEL SWITCH	*CF		L15H-3 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
284001 RIGHT	LOW FUEL LEVEL SWITCH	*CF		L15H-3 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
284002 LEFT	FUEL QUANTITY COMPENSATOR 9912019-4	*CF		300047-13001 13145P	MTH 31-Oct-1980		O/C			
284002 RIGHT	FUEL QUANTITY COMPENSATOR 9912019-4	*CF		300047-13001 13255P	MTH 31-Oct-1980		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **JALAIR LP**  
 Aircraft Model: **501 - MODEL 501**  
 Aircraft Serial: **501-0169** Unit: **0566** Reg No: **C-GFEE**  
 Airworthiness: **31-Oct-1980**  
 Print Date: **22-Aug-2012 7:10PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>17995.4</b>	<b>22037</b>	<b>18-Aug-2012</b>	<b>.02</b>
<b>ENG 1</b>	<b>8791.4</b>	<b>9226</b>	<b>18-Aug-2012</b>	<b>.03</b>
<b>ENG 2</b>	<b>7046.1</b>	<b>6912</b>	<b>18-Aug-2012</b>	<b>.03</b>

### Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
284003 LEFT WING	SECTION (61.00) FUEL QUANTITY PROBE 9912019-8	*CF		391046-218 1714D	MTH 31-Oct-1980		O/C			
284003 RIGHT WING	SECTION (61.00) FUEL QUANTITY PROBE 9912019-8	*CF		391046-218 1434D	MTH 31-Oct-1980		O/C			
284004 LEFT WING	SECTION (129.00) FUEL QUANTITY PROBE 9912019-7	*CF		391046-219 1812D	MTH 31-Oct-1980		O/C			
284004 RIGHT WING	SECTION (129.00) FUEL QUANTITY PROBE 9912019-7	*CF		391046-219 1762D	MTH 31-Oct-1980		O/C			
284005 LEFT WING	SECTION (171.50) FUEL QUANTITY PROBE 9912019-6	*CF		391046-220 1687D	MTH 31-Oct-1980		O/C			
284005 RIGHT WING	SECTION (171.50) FUEL QUANTITY PROBE 9912019-6	*CF		391046-220 1735D	MTH 31-Oct-1980		O/C			
284006 LEFT WING	SECTION (211.00) FUEL QUANTITY PROBE 9912019-5	*CF		391046-221 1748D	MTH 31-Oct-1980		O/C			
284006 RIGHT WING	SECTION (211.00) FUEL QUANTITY PROBE 9912019-5	*CF		391046-221 1809D	MTH 31-Oct-1980		O/C			
284007	FUEL QUANTITY INDICATOR 9912147-7			VSDL-OC203A 31ABF	MTH 16-Dec-1985		O/C			
284008	IND-FUEL REMAINING -- -	YTS		3265005-0101 808076	MTH 26-Jul-1984 HRS 4051		O/C	0		
291001	HYDRAULIC RESERVOIR 9912052-2	*CF		7140-150-2 1014	MTH 31-Oct-1980		O/C			
291002 NO. 1 ENGINE	HYDRAULIC PUMP 9912062-3	YTS		4120-004000 1094	MTH 24-Feb-1982 HRS 580		O/C	24		
291002 NO. 2 ENGINE	HYDRAULIC PUMP 9912062-3	*CF		4120-004000 191	MTH 31-Oct-1980		O/C			
291004 RIGHT	SUCTION SHUTOFF VALVE 9912062-3	*CF		149145 1637	MTH 31-Oct-1980		O/C			
291005	DUAL CHECK FLOW DETECTOR VALVE 9912194-3			3520020100-4 SN-UNKNOWN	MTH 26-Apr-1999 HRS 16262		O/C	0		
291014	HYDRAULIC SAFETY CHECK VALVE 9912062-3	*CF		262A4TB SN-UNKNOWN	MTH 31-Oct-1980		O/C			
301001 LEFT WING	DE-ICE BOOT 9912062-3			25S-7D5059-07 MK88350	MTH 20-Mar-2000 HRS 16648		O/C	0		
301002 RIGHT WING	DE-ICE BOOT 9912062-3			25S-7D5059-08 MK52060	MTH 20-Mar-2000 HRS 16648		O/C	0		
301003 LEFT	HORIZONTAL STABILIZER DE-ICE BOOT 9912062-3			25S-7D5059-03 MK88220	MTH 20-Mar-2000 HRS 16648		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **JALAIR LP**  
 Aircraft Model: **501 - MODEL 501**  
 Aircraft Serial: **501-0169** Unit: **0566** Reg No: **C-GFEE**  
 Airworthiness: **31-Oct-1980**  
 Print Date: **22-Aug-2012 7:10PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>17995.4</b>	<b>22037</b>	<b>18-Aug-2012</b>	<b>.02</b>
<b>ENG 1</b>	<b>8791.4</b>	<b>9226</b>	<b>18-Aug-2012</b>	<b>.03</b>
<b>ENG 2</b>	<b>7046.1</b>	<b>6912</b>	<b>18-Aug-2012</b>	<b>.03</b>

### Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
301003 RIGHT	HORIZONTAL STABILIZER DE-ICE BOOT			25S-7D5059-03 MK88260	MTH 20-Mar-2000 HRS 16648		O/C	0		
301004 VERTICAL STABILIZER	DE-ICE BOOT			25S-7D5059-05 MK51990	MTH 20-Mar-2000 HRS 16648		O/C	0		
301005 LEFT	ANTI-ICE ELEMENT 9912081-7	*CF		2E1469-1 165	MTH 31-Oct-1980		O/C			
301006 RIGHT	ANTI-ICE ELEMENT 9912081-8	*CF		2E1469-8 221	MTH 31-Oct-1980		O/C			
301007 AFT	DE-ICE PRESSURE SWITCH SWF			1106P55 2955	MTH 10-Aug-1989 HRS 9678		O/C	0		
301007 FORWARD	DE-ICE PRESSURE SWITCH	*CF		1106P55 993	MTH 31-Oct-1980		O/C			
301008 LEFT WING	DE-ICE VALVE	*CF		3D2353-06 N2740	MTH 31-Oct-1980		O/C			
301008 RIGHT WING	DE-ICE VALVE	*CF		3D2353-06 N2873	MTH 31-Oct-1980		O/C			
301008	STABILIZER AND FIN DE-ICE VALVE	*CF		3D2353-06 N2889	MTH 31-Oct-1980		O/C			
301009	AIRFOIL DE-ICE TIMER	*CF		76-1A 442	MTH 31-Oct-1980		O/C			
301010 LEFT WING	ANTI-ICE ASSEMBLY			5528007-15 420	MTH 31-Jan-1987 HRS 7311		O/C	0		
301010 RIGHT WING	ANTI-ICE ASSEMBLY	*CF		5528007-208 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
302001	ALCOHOL PUMP	*CF		476411 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
302002	BLEED AIR CHECK VALVE	*CF		85300 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
302003 LEFT	ANTI-ICE SOLENOID VALVE 9912086-1	YSC		320605 3576	MTH 15-Dec-2004 HRS 17673		O/C	0		
302003 RIGHT	ANTI-ICE SOLENOID VALVE 9912086-1			226395 213	MTH 14-Mar-1989 HRS 9395		O/C	2491		
302004 NO. 2 ENGINE	ANTI-ICE SWITCH			21548-2-19-6 SN-UNKNOWN	MTH 23-Feb-1988 HRS 8484		O/C	0		
303001 LEFT	PITOT TUBE	*CF		PH502 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
303001 RIGHT	PITOT TUBE	*CF		PH502 SN-UNKNOWN	MTH 31-Oct-1980		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **JALAIR LP**  
 Aircraft Model: **501 - MODEL 501**  
 Aircraft Serial: **501-0169** Unit: **0566** Reg No: **C-GFEE**  
 Airworthiness: **31-Oct-1980**  
 Print Date: **22-Aug-2012 7:10PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>17995.4</b>	<b>22037</b>	<b>18-Aug-2012</b>	<b>.02</b>
<b>ENG 1</b>	<b>8791.4</b>	<b>9226</b>	<b>18-Aug-2012</b>	<b>.03</b>
<b>ENG 2</b>	<b>7046.1</b>	<b>6912</b>	<b>18-Aug-2012</b>	<b>.03</b>

### Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
303002 LEFT LOWER	PILOT STATIC PORT	*CF		CM2933-5 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
303002 RIGHT LOWER	COPILOT STATIC PORT	*CF		CM2933-5 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
303003 LEFT UPPER	COPILOT STATIC PORT	*CF		CM2933-5 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
303003 RIGHT UPPER	PILOT STATIC PORT	*CF		CM2933-5 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
304001	HOT AIR TEMPERATURE MONITOR			1169-1 611	MTH 08-Apr-1985 HRS 5112		O/C	0		
304005	TEMPERATURE CONTROL VALVE 9912085-1	*CF		27241287 5F0119	MTH 31-Oct-1980		O/C			
304006	TEMPERATURE CONTROLLER 9912085-2	*CF		27231272 2F0153	MTH 31-Oct-1980		O/C			
304007 LEFT	TEMPERATURE SENSOR 9912085-3	*CF		27221274 9E0067	MTH 31-Oct-1980		O/C			
304007 RIGHT	TEMPERATURE SENSOR 9912085-3	*CF		27221274 2E0259	MTH 31-Oct-1980		O/C			
304008	PRESSURE SWITCH	*CF		1115P25 503	MTH 31-Oct-1980		O/C			
304009	WINDSHIELD ANTI-ICE BLEED AIR SOLENOID VALVE 9912086-2	*CF		226395-1 280	MTH 31-Oct-1980		O/C			
312001 AFT	DIGITAL CLOCK			811B SN-UNKNOWN	MTH 07-Mar-1986 HRS 6332		O/C	0		
312001 RIGHT	CLOCK 86000-1143	*CF		C664510-0102 W2850G	MTH 31-Oct-1980		O/C			
312001	CLOCK 86000-1143	YTS		C664510-0102 1162	MTH 18-Jan-1982 HRS 466		O/C	0		
313001	FLIGHT HOUR METER	*CF		15000 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
321001 LEFT MAIN LANDING GEAR	ASSEMBLY	*CF		5541000-11 558	MTH 31-Oct-1980		O/C			
321002 RIGHT MAIN LANDING GEAR	ASSEMBLY	*CF		5541000-12 565	MTH 31-Oct-1980		O/C			
322001 NOSE GEAR	ASSEMBLY			5542000-807 799	MTH 23-Feb-1988 HRS 8484 LDG 10775		O/C	0		
322002 NOSE LANDING GEAR	SHIMMY DAMPER			5543001-1 7075	MTH 22-Feb-1990 HRS 10247 LDG 12933		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **JALAIR LP**  
 Aircraft Model: **501 - MODEL 501**  
 Aircraft Serial: **501-0169** Unit: **0566** Reg No: **C-GFEE**  
 Airworthiness: **31-Oct-1980**  
 Print Date: **22-Aug-2012 7:10PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>17995.4</b>	<b>22037</b>	<b>18-Aug-2012</b>	<b>.02</b>
<b>ENG 1</b>	<b>8791.4</b>	<b>9226</b>	<b>18-Aug-2012</b>	<b>.03</b>
<b>ENG 2</b>	<b>7046.1</b>	<b>6912</b>	<b>18-Aug-2012</b>	<b>.03</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
322003 UPPER	NOSE TORQUE LNK ASSY --			5542302-1 SN-UNKNOWN	MTH 18-Sep-1987 HRS 8197 LDG 10405		23900	0	34305	12268
322004 NOSE LANDING GEAR	FORK	UVA		5542000-3 127	MTH 21-Jul-2011 HRS 17953.5 LDG 21983		O/C			
322005 NOSE LANDING GEAR	ACTUATOR FITTING	*CF		5511169-1 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
322006 LEFT NOSE LANDING GEAR	TRUNNION SUPPORT ASSEMBLY	*CF		5513056-5 SN-UNKNOWN	MTH 31-Oct-1980 LDG 0		22500	0	22500	463
322006 RIGHT NOSE LANDING GEAR	TRUNNION SUPPORT ASSEMBLY	*CF		5513056-6 SN-UNKNOWN	MTH 31-Oct-1980 LDG 0		22500	0	22500	463
322007 NOSE LANDING GEAR	TRUNION	*CF		5542301-5 SN-UNKNOWN	MTH 31-Oct-1980 LDG 0		22500	0	22500	463
322008 LEFT MAIN GEAR	TRUNNION ATTACH PIN	*CF		5541205-3 SN-UNKNOWN	MTH 31-Oct-1980 LDG 0	12246	28600	12246	28600	6563
322008 RIGHT MAIN GEAR	TRUNNION ATTACH PIN	*CF		5541205-4 SN-UNKNOWN	MTH 31-Oct-1980 LDG 0	12246	28600	12246	28600	6563
322009 LEFT MAIN GEAR	ACTUATOR PIN	*CF		6527213-2 SN-UNKNOWN	MTH 31-Oct-1980 LDG 0	12246	28600	12246	28600	6563
322009 RIGHT MAIN GEAR	ACTUATOR PIN	*CF		6527213-2 SN-UNKNOWN	MTH 31-Oct-1980 LDG 0	12246	28600	12246	28600	6563
322010 LEFT MAIN GEAR	ACTUATOR ATTACH STUD	*CF		6541204-2 SN-UNKNOWN	MTH 31-Oct-1980 LDG 0	12246	28600	12246	28600	6563
322010 RIGHT MAIN GEAR	ACTUATOR ATTACH STUD	*CF		6541204-2 SN-UNKNOWN	MTH 31-Oct-1980 LDG 0	12246	28600	12246	28600	6563
322011 LEFT MAIN GEAR	TRUNNION	*CF		5541306-3 SN-UNKNOWN	MTH 31-Oct-1980 LDG 0	12246	28600	12246	28600	6563
322011 RIGHT MAIN GEAR	TRUNNION	*CF		5541306-3 SN-UNKNOWN	MTH 31-Oct-1980 LDG 0	12246	28600	12246	28600	6563
322012 LEFT MAIN GEAR	AXLE	UVA		6541200-2 SN-UNKNOWN	MTH 21-Jul-2011 HRS 17953.5 LDG 21983		28600	0	50583	28546
322012 RIGHT MAIN GEAR	AXLE	*CF		6541200-1 SN-UNKNOWN	MTH 31-Oct-1980 LDG 0	12246	28600	12246	28600	6563
322013 LEFT MAIN GEAR	UPPER PISTON BEARING	*CF		5541310-3 SN-UNKNOWN	MTH 31-Oct-1980 LDG 0	12246	28600	12246	28600	6563
322013 RIGHT MAIN GEAR	UPPER PISTON BEARING	*CF		5541310-3 SN-UNKNOWN	MTH 31-Oct-1980 LDG 0	12246	28600	12246	28600	6563
322014 LEFT MAIN GEAR	UPPER TORQUE LINK	*CF		5541304-9 SN-UNKNOWN	MTH 31-Oct-1980 LDG 0	12246	28600	12246	28600	6563

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **JALAIR LP**  
 Aircraft Model: **501 - MODEL 501**  
 Aircraft Serial: **501-0169** Unit: **0566** Reg No: **C-GFEE**  
 Airworthiness: **31-Oct-1980**  
 Print Date: **22-Aug-2012 7:10PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>17995.4</b>	<b>22037</b>	<b>18-Aug-2012</b>	<b>.02</b>
<b>ENG 1</b>	<b>8791.4</b>	<b>9226</b>	<b>18-Aug-2012</b>	<b>.03</b>
<b>ENG 2</b>	<b>7046.1</b>	<b>6912</b>	<b>18-Aug-2012</b>	<b>.03</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
322014 RIGHT MAIN GEAR	UPPER TORQUE LINK	*CF		5541304-10 SN-UNKNOWN	MTH 31-Oct-1980 LDG 0	12246	28600	12246	28600	6563
322015 LEFT MAIN GEAR	LOWER TORQUE LINK	*CF		5541304-11 SN-UNKNOWN	MTH 31-Oct-1980 LDG 0	12246	28600	12246	28600	6563
322015 RIGHT MAIN GEAR 322015L : RL	LOWER TORQUE LINK	*CF		5541304-6 SN-UNKNOWN	MTH 31-Oct-1980 LDG 0	12246	41600	12246	41600	19563
322016 LEFT MAIN GEAR	TORQUE LINK SHAFT	*CF		6541212-2 SN-UNKNOWN	MTH 31-Oct-1980 LDG 0	12246	28600	12246	28600	6563
322016 RIGHT MAIN GEAR	TORQUE LINK SHAFT	*CF		6541212-2 SN-UNKNOWN	MTH 31-Oct-1980 LDG 0	12246	28600	12246	28600	6563
322017 LEFT MAIN GEAR	TORQUE LINK BOLT	*CF		5541220-2 SN-UNKNOWN	MTH 31-Oct-1980 LDG 0	12246	41600	12246	41600	19563
322017 RIGHT MAIN GEAR	TORQUE LINK BOLT	*CF		5541220-2 SN-UNKNOWN	MTH 31-Oct-1980 LDG 0	12246	41600	12246	41600	19563
322018 LEFT MAIN GEAR	TORQUE LINK NUT	*CF		MS17825-8 SN-UNKNOWN	MTH 31-Oct-1980 LDG 0	12246	28600	12246	28600	6563
322018 RIGHT MAIN GEAR	TORQUE LINK NUT	*CF		MS17825-8 SN-UNKNOWN	MTH 31-Oct-1980 LDG 0	12246	28600	12246	28600	6563
322019 NOSE GEAR	PISTON ASSEMBLY			5542105-1 224	MTH 28-Jun-1994 HRS 13525 LDG 17099		O/C	0		
322020 NOSE GEAR	CYLINDER BRAZE ASSEMBLY			5542100-3 SN-UNKNOWN	MTH 13-Jun-2000 HRS 16733 LDG 20795		22500	0	43295	21258
322021 NOSE GEAR	AXLE SPACER	UVA		5542223-1 SN-UNKNOWN	MTH 21-Jul-2011 HRS 17953.5 LDG 21983		22500	0	44483	22446
322022 NOSE GEAR	TORQUE LINK SHAFT			5542208-3 1094	MTH 28-Jun-1994 HRS 13525 LDG 17099		22500	0	39599	17562
323001 LEFT MAIN LANDING GEAR	ACTUATOR ASSEMBLY 9912053-17	YTS		2-7442-1 010169	MTH 21-Aug-1982 HRS 1153 LDG 1391		37500	0	38891	16854
323002 RIGHT MAIN LANDING GEAR	ACTUATOR ASSEMBLY 9912053-18			1523100-2 50B	MTH 22-Jan-1995 HRS 13971 LDG 17654		37500	17471	37683	15646
323003 NOSE LANDING GEAR	ACTUATOR ASSEMBLY 9912063-13			1523200-1 55	MTH 20-Apr-1992 HRS 11952 LDG 15111		32600	9022	38689	16652
323004 LEFT MAIN LANDING GEAR	UPLOCK ACTUATOR			5527504-2 166	MTH 26-Jun-1986 HRS 6703 LDG 8465		O/C	0		
323004 NOSE LANDING GEAR	UPLOCK ACTUATOR	*CF		5527504-2 CE2297	MTH 31-Oct-1980		O/C			
323004 RIGHT MAIN LANDING GEAR	UPLOCK ACTUATOR	*CF		5527504-2 CE2101	MTH 31-Oct-1980		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.





# CESCOM 10 - Aircraft Status Report

Owner: **JALAIR LP**  
 Aircraft Model: **501 - MODEL 501**  
 Aircraft Serial: **501-0169** Unit: **0566** Reg No: **C-GFEE**  
 Airworthiness: **31-Oct-1980**  
 Print Date: **22-Aug-2012 7:10PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>17995.4</b>	<b>22037</b>	<b>18-Aug-2012</b>	<b>.02</b>
<b>ENG 1</b>	<b>8791.4</b>	<b>9226</b>	<b>18-Aug-2012</b>	<b>.03</b>
<b>ENG 2</b>	<b>7046.1</b>	<b>6912</b>	<b>18-Aug-2012</b>	<b>.03</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
323006	EMERGENCY GEAR AIR BOTTLE 9912103-1	UNK		23111321 2033	MTH 08-Nov-2011 HRS 17973.7		180	0	28-Feb-2023	126 m 6 d
Manufacture Date: 29-Feb-2008										
323007	LANDING GEAR CONTROL VALVE YTS			2710969 1098	MTH 29-Oct-1981 HRS 323 LDG 459		O/C	0		
323008	CYLINDER ASSEMBLY RIGHT MAIN LANDING GEAR			5541109-6 SN-UNKNOWN	MTH 11-Mar-1993 HRS 12655 LDG 16005		16100	0	32105	10068
323014	CYLINDER ASSEMBLY LEFT MAIN LANDING GEAR			5541109-5 SN-UNKNOWN	MTH 11-Mar-1993 HRS 12655 LDG 16005		16100	0	32105	10068
323018	PISTON WELD ASSEMBLY LEFT MAIN LANDING GEAR			5541108-5 SN-UNKNOWN	MTH 11-Mar-1993 HRS 12655 LDG 16005		15000	0	31005	8968
323018	PISTON WELD ASSEMBLY RIGHT MAIN LANDING GEAR			5541108-6 SN-UNKNOWN	MTH 11-Mar-1993 HRS 12655 LDG 16005		15000	0	31005	8968
323019	EMERGENCY AIR BOTTLE GAGE *CF			2341128 SN-UNKNOWN	MTH 31-Oct-1980		O/C	0		
324001	WHEEL ASSEMBLY LEFT MAIN LANDING GEAR			5001477-3 87040867	MTH 21-Jan-2002 HRS 17253 LDG 21294		O/C	0		
324001	WHEEL ASSEMBLY RIGHT MAIN LANDING GEAR			5001477-3 77080605	MTH 18-May-1999 HRS 16278 LDG 20343		O/C	1219		
324002	WHEEL ASSEMBLY NOSE LANDING GEAR			9914069-2 3-1418 02570457	MTH 05-May-2002 HRS 17381 LDG 21387		O/C	0		
324003	BRAKE ASSEMBLY LEFT MAIN LANDING GEAR	UNK		5001446-6 S-MAR95-75	MTH 15-Jun-2010 HRS 17990.9		O/C	0	0	
<i>324003T : LTR</i>										
324004	BRAKE ASSEMBLY RIGHT MAIN LANDING GEAR	UNK		5001446-6 JUL97-93	MTH 15-Jun-2010 HRS 17990.9		O/C	0	0	
<i>324004T : RTR</i>										
324005	TIRE LEFT MAIN GEAR			220K08-2 SN-UNKNOWN	MTH 26-Aug-2001 HRS 17112 LDG 21149		O/C	0		
<i>324005T : LTR</i>										
324005	TIRE RIGHT MAIN GEAR			220K08-3 03001137	MTH 21-Sep-1999 HRS 16424 LDG 20498		O/C	0		
<i>324005T : RTR</i>										
324006	TIRE NOSE LANDING GEAR	UVA		184F10-2 02442916	MTH 21-Jul-2011 HRS 17953.5 LDG 21983		O/C	0	0	0
324011	BRAKE MASTER CYLINDER COPILOT INBOARD		*CF	12A085-9 1577	MTH 31-Oct-1980		O/C			
324011	BRAKE MASTER CYLINDER PILOT OUTBOARD			12A085-11 0701	MTH 23-Feb-1988 HRS 8484 LDG 10775		O/C	0		
324012	BRAKE MASTER CYLINDER COPILOT OUTBOARD			12A085-12 0782	MTH 23-Feb-1988 HRS 8484 LDG 10775		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **JALAIR LP**  
 Aircraft Model: **501 - MODEL 501**  
 Aircraft Serial: **501-0169** Unit: **0566** Reg No: **C-GFEE**  
 Airworthiness: **31-Oct-1980**  
 Print Date: **22-Aug-2012 7:10PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>17995.4</b>	<b>22037</b>	<b>18-Aug-2012</b>	<b>.02</b>
<b>ENG 1</b>	<b>8791.4</b>	<b>9226</b>	<b>18-Aug-2012</b>	<b>.03</b>
<b>ENG 2</b>	<b>7046.1</b>	<b>6912</b>	<b>18-Aug-2012</b>	<b>.03</b>

### Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
324012 PILOT INBOARD	BRAKE MASTER CYLINDER 9912050-10	*CF		12A085-10 1602	MTH 31-Oct-1980		O/C			
324013	PARKING BRAKE VALVE	*CF		AS20800-1 675	MTH 31-Oct-1980		O/C	0		
324014	EMERGENCY BRAKE VALVE 9912105-1	*CF		53640 251A	MTH 31-Oct-1980		O/C			
326001	GEAR WARNING HORN 9910080-1	*CF		A2948 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
331001	ANNUNCIATOR PANEL 9912167-11	YTS		D3474-11 2238	MTH 30-Sep-1981 HRS 246		O/C	0		
331011	ELECTRICAL PANEL LIGHT INVERTER			EM2044-1 759	MTH 25-May-1989 HRS 9609		O/C	0		
331012	MASTER WARNING SWITCH *CF			1941-4 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
334002	VERTICAL FIN ANTI-COLLISION LIGHT			40-0100-1 4618	MTH 02-Nov-1992 HRS 12373		O/C		12373	
334003 LEFT	STROBE POWER SUPPLY YTS			60-1755-5 5622	MTH 05-Aug-1982 HRS 1095		O/C	14		
334003 RIGHT	STROBE POWER SUPPLY *CF			60-1755-5 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
335001	EMERGENCY LIGHTING BATTERY			6518109-7 SN-UNKNOWN	MTH 23-Feb-1988 HRS 8484		O/C	0		
341001 LEFT	AIRSPEED INDICATOR UVA			10-51002-3 263251	MTH 25-Jan-2000		O/C			
341001 RIGHT	AIRSPEED INDICATOR UVA			10-51002-13 263252	MTH 25-Jan-2000		O/C			
341002 COPILOT	ALTIMETER YUL			570-24929-013 1192	MTH 01-Sep-2004 HRS 17657		O/C	3974		
341002 PILOT	ALTIMETER BA-141 YUL			4016341-905 93077525	MTH 01-Sep-2004 HRS 17657		O/C	360		
341002 STANDBY	ALTIMETER UVA			24929-013 1192	MTH 21-Jul-2011 HRS 17953.5 LDG 21983		O/C			
341003 <i>341002 : ENCOD</i>	ENCODING ALTIMETER 9914549-1 UVA			570-24929-013 1192	MTH 25-Jan-2000		O/C			
341004	OUTSIDE AIR TEMPERATURE GAUGE 162BL507D *CF			C668510-0401 1597	MTH 31-Oct-1980		O/C			
341005	OVERSPEED WARNING SWITCH 9912076-9 *CF			DRA45C-39 267	MTH 31-Oct-1980		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **JALAIR LP**  
 Aircraft Model: **501 - MODEL 501**  
 Aircraft Serial: **501-0169** Unit: **0566** Reg No: **C-GFEE**  
 Airworthiness: **31-Oct-1980**  
 Print Date: **22-Aug-2012 7:10PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>17995.4</b>	<b>22037</b>	<b>18-Aug-2012</b>	<b>.02</b>
<b>ENG 1</b>	<b>8791.4</b>	<b>9226</b>	<b>18-Aug-2012</b>	<b>.03</b>
<b>ENG 2</b>	<b>7046.1</b>	<b>6912</b>	<b>18-Aug-2012</b>	<b>.03</b>

### Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
341006	OVERSPEED WARNING HORN *CF			SC628H SN-UNKNOWN	MTH 31-Oct-1980		O/C			
341010	ANGLE OF ATTACK INDICATOR *CF			SLZ9686-1 PC1449	MTH 31-Oct-1980		O/C			
341012	ANGLE OF ATTACK POTENTIOMETER *CF			MOD202-5K SN-UNKNOWN	MTH 31-Oct-1980		O/C			
341013	ANGLE OF ATTACK TRANSMITTER YTS			SLZ9386 U0814C	MTH 16-Sep-1983 HRS 2802		O/C	0		
341014	ANGLE OF ATTACK INDEXER *CF			SLZ9374 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
341020	VERTICAL NAVIGATIONAL CONTROLLER/ VN-212			4020571-904 82071771	MTH 31-Aug-1994 HRS 13748		O/C	1397		
341021	RADIO ALTIMETER INDICATOR RA-215			4014267-903 77061530	MTH 04-Jul-1991 HRS 11224		O/C	2384		
342001	MAGNETIC COMPASS UVA			C660501-0301 SN-UNKNOWN	MTH 21-Jul-2011 HRS 17953.5 LDG 21983		O/C	0 0 0		
342002 RIGHT	TURN & BANK INDICATOR *CF			C661004-0101 825	MTH 31-Oct-1980		O/C			
342003 RIGHT	HORIZON GYRO 1U149-002-2			C661056-0202 33595C	MTH 12-Oct-1992 HRS 12351		O/C	0		
342021 LEFT	VERTICAL SPEED INDICATOR			C661006-0101 W9718G	MTH 11-Dec-1987 HRS 8427		O/C	8427		
342021 RIGHT	VERTICAL SPEED INDICATOR			C661006-0101 13802	MTH 26-Jan-1992 HRS 11760		O/C	348		
342041 NO. 2	FLIGHT DIRECTOR COMPUTER FZ-500 *CF			4018369-905 081910	MTH 31-Oct-1980		O/C			
342042 LEFT	AP/FD MODE MSE-215 INDICATOR *CF			4020570-901 050804	MTH 31-Oct-1980		O/C			
342043 NO. 1	VERTICAL GYRO VG-14A			7000622-901 82013882	MTH 16-Apr-1994 HRS 13446		O/C	4994		
342043 NO. 2	VERTICAL GYRO VG-14A			7000622-901 80031275	MTH 01-Mar-1994 HRS 13334		O/C	32		
342044 LEFT	RATE GYRO RG-204			7007453-903 93083444	MTH 02-Dec-1993 HRS 13236		O/C	0		
342045 NO. 1	ADI INDICATOR AD-600			4020547-906 79050608	MTH 08-May-1990 HRS 10410		O/C	1260		
342048 NO. 1	AIR DATA COMPUTER AZ-241			4013241-901 80051276	MTH 06-Aug-2002 HRS 17482		O/C	-2055		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **JALAIR LP**  
 Aircraft Model: **501 - MODEL 501**  
 Aircraft Serial: **501-0169** Unit: **0566** Reg No: **C-GFEE**  
 Airworthiness: **31-Oct-1980**  
 Print Date: **22-Aug-2012 7:10PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>17995.4</b>	<b>22037</b>	<b>18-Aug-2012</b>	<b>.02</b>
<b>ENG 1</b>	<b>8791.4</b>	<b>9226</b>	<b>18-Aug-2012</b>	<b>.03</b>
<b>ENG 2</b>	<b>7046.1</b>	<b>6912</b>	<b>18-Aug-2012</b>	<b>.03</b>

### Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
342049 LEFT	DIR GYRO SYN COMPASS C-14D			4020577-3 82062752	MTH 13-Jun-2000 HRS 16733		O/C	0		
342049 RIGHT	DIR GYRO SYN COMPASS			4020577-3 81072280	MTH 25-Mar-1990 HRS 10306		O/C	1691		
342050 NO. 1	FLUX VALVE FX-220	*CF		2594484 063457	MTH 31-Oct-1980		O/C			
342050 NO. 2	FLUX VALVE FX-220	*CF		2594484 063456	MTH 31-Oct-1980		O/C			
342052	DUAL REMOTE COMPENSATOR CS-412	*CF		2593379-1 064812	MTH 31-Oct-1980		O/C			
342053 NO. 1	HSI INDICATOR RD-600			4020553-901 78110385	MTH 06-Feb-1994 HRS 13278		O/C	0		
342054 RIGHT	HSI --			4020553-901 80010545	MTH 06-May-1991 HRS 11120		O/C	0		
342064 STANDBY	GYRO POWER SUPPLY	UNK		501-1075-01 1267	MTH 24-May-2012 HRS 17989.4		O/C	1155.4		
342065 STANDBY	GYRO			501-1105-04 5115	MTH 12-Apr-1994 HRS 13441		O/C	12990		
344018	WEATHER RADAR INDICATOR IN-1102	YTS		4000964-0203 1461	MTH 24-Feb-1982 HRS 580		O/C	104		
344019	RADAR-RCVR/XMTR -- RT-131A	YTS		4000763-3101 5600	MTH 23-May-1984 HRS 3742		O/C	0		
344020	RADAR ANTENNA -- DA-1230A			4000504-0301 6473	MTH 11-Aug-1989 HRS 9681		O/C	0		
344021 NO. 1	RADIO MAGNETIC INDICATOR 332C-10			622-0555-008 7925	MTH 11-Apr-1988 HRS 8626		O/C	693		
344021 NO. 2	RADIO MAGNETIC INDICATOR 332C-10			622-0555-008 8953	MTH 06-Apr-1988 HRS 8615		O/C	8615		
344022	RADIO ALTIMETER TRANSCEIVER RT-220			4004437-901 80093725	MTH 04-Jul-1991 HRS 11224		O/C	4721		
344023 AFT	RADIO ALTITUDE ANTENNA AT-224	*CF		4010504 041276	MTH 31-Oct-1980		O/C			
344023 FORWARD	RADIO ALTITUDE ANTENNA AT-224	*CF		4010504 041288	MTH 31-Oct-1980		O/C			
345004 NO. 1	ATC TRANSPONDER ANTENNA	*CF		DMN150-2 13977	MTH 31-Oct-1980		O/C			
345004 NO. 2	ATC TRANSPONDER ANTENNA	*CF		DMN150-2 10261	MTH 31-Oct-1980		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **JALAIR LP**  
 Aircraft Model: **501 - MODEL 501**  
 Aircraft Serial: **501-0169** Unit: **0566** Reg No: **C-GFEE**  
 Airworthiness: **31-Oct-1980**  
 Print Date: **22-Aug-2012 7:10PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>17995.4</b>	<b>22037</b>	<b>18-Aug-2012</b>	<b>.02</b>
<b>ENG 1</b>	<b>8791.4</b>	<b>9226</b>	<b>18-Aug-2012</b>	<b>.03</b>
<b>ENG 2</b>	<b>7046.1</b>	<b>6912</b>	<b>18-Aug-2012</b>	<b>.03</b>

### Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
345007 NO. 1	DME ANTENNA	*CF		DMNI50-2 12926	MTH 31-Oct-1980		O/C			
345008 NO. 1	COURSE DEVIATION INDICATOR	*CF		520850 973	MTH 31-Oct-1980		O/C			
345010	NAV ANTENNA KIT	*CF		DMN4-17-1B 14106	MTH 31-Oct-1980		O/C			
345011 NO. 1	ADF RECEIVER ADF-60A	UNK		622-2362-001 11221	MTH 24-May-2012 HRS 17989.4		O/C			
345011 NO. 2	ADF RECEIVER ADF-60A			622-2362-001 25840	MTH 06-Oct-1989 HRS 9895		O/C	0		
345012 NO. 1	ADF CONTROL			156MI 1519	MTH 31-Jul-1991 HRS 11345		O/C	0		
345012 NO. 2	ADF CONTROL			156MI 1426	MTH 31-Jul-1991 HRS 11345		O/C	0		
345014 NO. 1	ADF LOOP ANTENNA APA-80			622-2363-001 28117	MTH 17-Aug-2001 HRS 17100		O/C	0		
345014 NO. 2	ADF LOOP ANTENNA APA-80			622-2363-001 5011	MTH 17-Aug-2001 HRS 17100		O/C	1507		
345018 RIGHT	ANTENNA-RNAV --			27010045 18937	MTH 04-Jul-1991 HRS 11224		O/C	0		
345018	GLIDESLOPE ANTENNA	*CF		RGS1048 6147	MTH 31-Oct-1980		O/C			
345020 RIGHT	LORAN RECEIVER			25410036 29201	MTH 04-Jul-1991 HRS 11224		O/C	0		
345032 BOTTOM	NO. 2 NAVIGATION <del>RECEIVER</del>			622-0876-001 8958	MTH 12-Mar-1993 HRS 12661		O/C	0		
345032 TOP	NO. 1 NAVIGATION RECEIVER VIR-30	YTS		622-0876-001 14740	MTH 13-Jun-1983 HRS 2341		O/C	2116		
345034 NO. 1	ATC TRANSPONDER TDR-90	YUL		622-1270-001 10678	MTH 01-Sep-2004 HRS 17657		O/C	1332		
345034 NO. 2	ATC TRANSPONDER TDR-90	YUL		622-1270-001 12375	MTH 01-Sep-2004 HRS 17657		O/C	0		
345035 NO. 1	DME INDICATOR			622-2012-201 1813	MTH 18-Dec-1990 HRS 10878		O/C	6748		
345036 NO. 2	DME INTERROGATOR			622-1233-001 9219	MTH 18-Dec-1990 HRS 10878		O/C	10609		
345038 LEFT	ADF CONTROL --			156M1 21519	MTH 23-Oct-1989 HRS 9954		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **JALAIR LP**  
 Aircraft Model: **501 - MODEL 501**  
 Aircraft Serial: **501-0169** Unit: **0566** Reg No: **C-GFEE**  
 Airworthiness: **31-Oct-1980**  
 Print Date: **22-Aug-2012 7:10PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>17995.4</b>	<b>22037</b>	<b>18-Aug-2012</b>	<b>.02</b>
<b>ENG 1</b>	<b>8791.4</b>	<b>9226</b>	<b>18-Aug-2012</b>	<b>.03</b>
<b>ENG 2</b>	<b>7046.1</b>	<b>6912</b>	<b>18-Aug-2012</b>	<b>.03</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
345053	VLF ANTENNA	YTS		11305-2 2017	MTH 06-Mar-1983 HRS 1908		O/C	0		
345054	VLF CONTROL DISPLAY	*CF		10060-6 2058	MTH 31-Oct-1980		O/C			
345055	VLF COURSE DEVIATION INDICATOR	*CF		10070-1 998	MTH 31-Oct-1980		O/C			
345056	VLF RECEIVER COMPUTER UNIT	*CF		10050-3-211 1441	MTH 31-Oct-1980		O/C			
345057	VLF OPERATIONAL EQUIPMENT UNIT	*CF		10600-1-102 1829	MTH 31-Oct-1980		O/C			
345118	GPS <del>KANTENNA</del>			071-01553-0200 32366	MTH 17-Aug-2001 HRS 17100		O/C	0		
345132	GPS RECEIVER/ <del>SENSOR</del>			066-04031-1321 24487	MTH 26-Aug-2001 HRS 17112		O/C	0		
351001	OXYGEN PRESSURE GAUGE MD-97	*CF		C668512-0101 W8159G	MTH 31-Oct-1980		O/C	0		
351004 COPILOT	OXYGEN MASK 9912057-3			ZMR140 SN-UNKNOWN	MTH 30-Nov-1987 HRS 8403		O/C	0		
351004 PILOT	OXYGEN MASK 9912057-3	TOL		ZMR140 7861	MTH 13-Nov-1981 HRS 345		O/C	0		
351005	OXYGEN REGULATOR 9912057-2			ZR807 4762	MTH 12-Sep-2008 HRS 17864		O/C	0		
351006	OXYGEN CYLINDER ZC369-64	UNK		176176-64 4762-K906509	MTH 08-Nov-2011 HRS 17973.7		288	0	30-Nov-2035	279 m 8 d
361001	DOOR SEAL CONTROL VALVE	*CF		MJV3 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
361002	INSTRUMENT REGULATOR 9912043-1	YSC		38E85-4C 445U	MTH 10-Aug-2004 HRS 17657		O/C	0		
361003	DEICE BOOT REGULATOR 9912043-2	YSC		38E85-5C RF2287	MTH 10-Aug-2004 HRS 17657		O/C	0		
361004	PNEUMATIC (BLEED AIR) PRESSURE REGULATOR	*CF		2102702-5 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
361006	FORWARD INSTRUMENT BLEED AIR PRESSURE REGULATOR			3H64-7 11AC	MTH 05-Jul-1988 HRS 8912		O/C	0		
521001 CABIN	DOOR SEAL 9912075-3	*CF		S15501 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
526001 CABIN	DOOR STEP	*CF		6519009-25 360	MTH 31-Oct-1980		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **JALAIR LP**  
 Aircraft Model: **501 - MODEL 501**  
 Aircraft Serial: **501-0169** Unit: **0566** Reg No: **C-GFEE**  
 Airworthiness: **31-Oct-1980**  
 Print Date: **22-Aug-2012 7:10PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>17995.4</b>	<b>22037</b>	<b>18-Aug-2012</b>	<b>.02</b>
<b>ENG 1</b>	<b>8791.4</b>	<b>9226</b>	<b>18-Aug-2012</b>	<b>.03</b>
<b>ENG 2</b>	<b>7046.1</b>	<b>6912</b>	<b>18-Aug-2012</b>	<b>.03</b>

### Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
561001 LEFT MAIN	WINDSHIELD 9912064-7	SWF		CES-507-017-0 615512	MTH 10-Aug-1989 HRS 9678		O/C	9678		
561002 RIGHT MAIN	WINDSHIELD 9912064-8	SWF		CES-507-018-0 H76210	MTH 10-Aug-1989 HRS 9678		O/C	9678		
561003	FOUL WEATHER WINDOW			5511275-7 379	MTH 04-Jul-1991 HRS 11224		O/C	0		
561005 COPILOT INBOARD	WINDOW	*CF		5511285-6 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
561005 COPILOT OUTBOARD	WINDOW	*CF		5511285-4 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
561005 PILOT INBOARD	WINDOW	*CF		5511285-5 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
561005 PILOT OUTBOARD	WINDOW	*CF		5511285-3 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
562001 LEFT AFT	CABIN WINDOW	*CF		5591005-5 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
562001 LEFT CENTER AFT	CABIN WINDOW	*CF		5591005-5 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
562001 LEFT CENTER FORWARD	CABIN WINDOW	*CF		5591005-5 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
562001 LEFT FORWARD	CABIN MAIN DOOR WINDOW	*CF		5591005-6 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
562001 RIGHT AFT	CABIN WINDOW	*CF		5591005-5 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
562001 RIGHT CENTER AFT	CABIN WINDOW	*CF		5591005-5 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
562001 RIGHT CENTER FORWARD	CABIN WINDOW	*CF		5591005-5 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
562001 RIGHT FORWARD	CABIN EMERGENCY DOOR WINDOW	*CF		5591005-5 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
572001 LEFT FORWARD	TRUNNION FITTING ASSEMBLY			5522700-1 SN-UNKNOWN	MTH 11-Apr-2006 HRS 17720 LDG 21747		20000	0	41747	19710
572002 RIGHT FORWARD	TRUNNION FITTING ASSEMBLY			5522700-2 SN-UNKNOWN	MTH 11-Apr-2006 HRS 17720 LDG 21747		20000	0	41747	19710
574001 LEFT AFT	TRUNNION FITTING ASSEMBLY	*CF		5522710-1 SN-UNKNOWN	MTH 31-Oct-1980 LDG 0		41600	0	41600	19563
574002 RIGHT AFT	TRUNNION FITTING ASSEMBLY	*CF		5522710-2 SN-UNKNOWN	MTH 31-Oct-1980 LDG 0		41600	0	41600	19563

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **JALAIR LP**  
 Aircraft Model: **501 - MODEL 501**  
 Aircraft Serial: **501-0169** Unit: **0566** Reg No: **C-GFEE**  
 Airworthiness: **31-Oct-1980**  
 Print Date: **22-Aug-2012 7:10PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>17995.4</b>	<b>22037</b>	<b>18-Aug-2012</b>	<b>.02</b>
<b>ENG 1</b>	<b>8791.4</b>	<b>9226</b>	<b>18-Aug-2012</b>	<b>.03</b>
<b>ENG 2</b>	<b>7046.1</b>	<b>6912</b>	<b>18-Aug-2012</b>	<b>.03</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
574003 LEFT	SIDEBRACE FITTING ASSEMBLY *CF			5522720-1 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
574004 RIGHT	SIDEBRACE FITTING ASSEMBLY *CF			5522720-2 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
710002 LEFT ENGINE	BY-PASS NOZZLE ASSEMBLY YTS			5555030-18 SN-UNKNOWN	MTH 11-Nov-1983 HRS 2998		O/C	0		
710002 RIGHT ENGINE	BY-PASS NOZZLE ASSEMBLY YTS			5555030-18 SN-UNKNOWN	MTH 29-Oct-1983 HRS 2964		O/C	0		
712001 LEFT ENGINE AFT	ISOLATOR MOUNT 9912028-2			LM420SA6 0590	MTH 06-Sep-1996 HRS 15384		3500	0	18884	888.6
712001 RIGHT ENGINE AFT	ISOLATOR MOUNT 9912028-2	UVA		LM420SA6 061465	MTH 13-Jul-2011 HRS 17953.5 LDG 21983		3500	3336.3	18117.2	121.8
712002 LEFT ENGINE FORWARD BOTTOM	ISOLATOR MOUNT 9912028-3			LM420SA5 1141	MTH 06-Sep-1996 HRS 15384		3500	0	18884	888.6
712002 LEFT ENGINE FORWARD TOP	ISOLATOR MOUNT 9912028-3			LM420SA5 1117	MTH 06-Sep-1996 HRS 15384		3500	0	18884	888.6
712002 RIGHT ENGINE FORWARD BOTTOM	ISOLATOR MOUNT 9912028-3	UVA		LM420SA5 053120	MTH 13-Jul-2011 HRS 17953.5 LDG 21983		3500	3336.3	18117.2	121.8
712002 RIGHT ENGINE FORWARD TOP	ISOLATOR MOUNT 9912028-3	UVA		LM420SA5 053107	MTH 13-Jul-2011 HRS 17953.5 LDG 21983		3500	3336.3	18117.2	121.8
71EN1 NO. 1 <i>710001 : E1**L</i>	ENGINE 3018700			JT15D-1B 76879	MTH 30-Jun-1997 HRS 15654		E/C	0		
71EN2 NO. 2 <i>710001 : E2**R</i>	ENGINE 3018700	UVA		JT15D-1A 77040LNR	MTH 13-Jul-2011 HRS 17953.5 LDG 21983		E/C	7004.2		
722001 E1	OIL PUMP			3030391 SN-UNKNOWN	MTH 30-Jun-1997 HRS 15654		O/C	0		
722001 E2	OIL PUMP			3030391 SN-UNKNOWN	MTH 13-Jul-2011 HRS 17953.5 LDG 21983		O/C	0 3336.3 0		
723001 E1	FAN			3018020 SN-UNKNOWN	MTH 30-Jun-1997 HRS 15654		O/C	0		
723001 E2	FAN			3018020 SN-UNKNOWN	MTH 13-Jul-2011 HRS 17953.5 LDG 21983		O/C	0 3336.3 0		
723010 E1	CENTRIFUGAL IMPELLER			3032070 6F907	MTH 30-Jun-1997 HRS 15654 LDG 19709		8400	0	28109	6072
723010 E2	CENTRIFUGAL IMPELLER			3020365 SN-UNKNOWN	MTH 13-Jul-2011 HRS 17953.5 LDG 21983			0 0 6858		
723030 E1	LOW PRESSURE COMPRESSOR HUB			3018018 7E837	MTH 30-Jun-1997 HRS 15654 LDG 19709		13750	6898	26561	4524

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.





# CESCOM 10 - Aircraft Status Report

Owner: **JALAIR LP**  
 Aircraft Model: **501 - MODEL 501**  
 Aircraft Serial: **501-0169** Unit: **0566** Reg No: **C-GFEE**  
 Airworthiness: **31-Oct-1980**  
 Print Date: **22-Aug-2012 7:10PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>17995.4</b>	<b>22037</b>	<b>18-Aug-2012</b>	<b>.02</b>
<b>ENG 1</b>	<b>8791.4</b>	<b>9226</b>	<b>18-Aug-2012</b>	<b>.03</b>
<b>ENG 2</b>	<b>7046.1</b>	<b>6912</b>	<b>18-Aug-2012</b>	<b>.03</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
723030 E2	LOW PRESSURE COMPRESSOR HUB			3018018 SN-UNKNOWN	MTH 13-Jul-2011 HRS 17953.5 LDG 21983		13750	0 0 6858	28875	6838
725010 E1	HIGH PRESSURE TURBINE ROTOR DISK			3023411 6E875	MTH 30-Jun-1997 HRS 15654 LDG 19709		14000	0 0 6898	26811	4774
725010 E2	HIGH PRESSURE TURBINE ROTOR DISK			3023411 SN-UNKNOWN	MTH 13-Jul-2011 HRS 17953.5 LDG 21983		14000	0 0 6858	29125	7088
725020 E1	SECOND STAGE LOW PRESSURE TURBINE ROTOR DISK			3022212 8D725	MTH 30-Jun-1997 HRS 15654 LDG 19709		14000	0 0 6898	26811	4774
725020 E2	SECOND STAGE LOW PRESSURE TURBINE ROTOR DISK			3022212 SN-UNKNOWN	MTH 13-Jul-2011 HRS 17953.5 LDG 21983		14000	0 0 6858	29125	7088
725030 E1	THIRD STAGE LOW PRESSURE TURBINE ROTOR DISK			3021213 5E792	MTH 30-Jun-1997 HRS 15654 LDG 19709		14000	0 0 6898	26811	4774
725030 E2	THIRD STAGE LOW PRESSURE TURBINE ROTOR DISK			3021213 SN-UNKNOWN	MTH 13-Jul-2011 HRS 17953.5 LDG 21983		14000	0 0 6858	29125	7088
725071 E1	COMBUSTION LINER			3029994 SN-UNKNOWN	MTH 30-Jun-1997 HRS 15654		O/C	0		
725071 E2	COMBUSTION LINER			3022474 SN-UNKNOWN	MTH 13-Jul-2011 HRS 17953.5 LDG 21983		O/C	0 3336.3 0		
732002	ENGINE SYNCHRONIZER CONTROL			213723 1825417	MTH 06-Aug-1987 HRS 8034		O/C	0		
732003	ENGINE SYNCHRONIZER ACTUATOR *CF			5485-066 20419A	MTH 31-Oct-1980		O/C			
733002	FUEL FLOW INDICATOR 9912147-17			VSDL-OC408D 101CA	MTH 01-Jun-1999 HRS 16295		O/C	10511		
733003 NO. 1 ENGINE	FUEL FLOWMETER 9912031-4			3268005-0101 0050	MTH 21-Jun-1988 HRS 8853		O/C	1260		
733003 NO. 2 ENGINE	FUEL FLOWMETER 9912031-4	YTS		3268005-0101 4692	MTH 08-Nov-1982 HRS 1429		O/C	105		
731010 E1	FUEL PUMP 3026909			025493-401-05 2069	MTH 30-Jun-1997 HRS 15654		O/C	0		
731010 E2	FUEL PUMP 3026909			025493-401-05 SN-UNKNOWN	MTH 13-Jul-2011 HRS 17953.5 LDG 21983		O/C	0 3336.3 0		
731020 E1	FUEL-OIL COOLER 3015303			UA530768-4 1944	MTH 30-Jun-1997 HRS 15654		O/C	0		
731020 E2	FUEL-OIL COOLER 3015303			UA530768-4 1167	MTH 13-Jul-2011 HRS 17953.5 LDG 21983		O/C	0 0 0		



# CESCOM 10 - Aircraft Status Report

Owner: **JALAIR LP**  
 Aircraft Model: **501 - MODEL 501**  
 Aircraft Serial: **501-0169** Unit: **0566** Reg No: **C-GFEE**  
 Airworthiness: **31-Oct-1980**  
 Print Date: **22-Aug-2012 7:10PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>17995.4</b>	<b>22037</b>	<b>18-Aug-2012</b>	<b>.02</b>
<b>ENG 1</b>	<b>8791.4</b>	<b>9226</b>	<b>18-Aug-2012</b>	<b>.03</b>
<b>ENG 2</b>	<b>7046.1</b>	<b>6912</b>	<b>18-Aug-2012</b>	<b>.03</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
731030 E1	MOTIVE FLOW VALVE 3017930			2524995 SN-UNKNOWN	MTH 30-Jun-1997 HRS 15654		O/C	0		
731030 E2	MOTIVE FLOW VALVE 3017930			2524995 SN-UNKNOWN	MTH 13-Jul-2011 HRS 17953.5 LDG 21983		O/C	0 3336.3 0		
731040 E1	FLOW DIVIDER VALVE 3024476			25607-2 2069	MTH 30-Jun-1997 HRS 15654		O/C	0		
731040 E2	FLOW DIVIDER VALVE 3024476			25607-1 SN-UNKNOWN	MTH 13-Jul-2011 HRS 17953.5 LDG 21983		O/C	0 3336.3 0		
732010 E1	FUEL CONTROL UNIT 3030251			3244763-1 A60315	MTH 30-Jun-1997 HRS 15654		O/C	0		
732010 E2	FUEL CONTROL UNIT 3030251			3244763-1 SN-UNKNOWN	MTH 13-Jul-2011 HRS 17953.5 LDG 21983		O/C	0 3336.3 0		
741010 E1 LOWER	IGNITION EXCITER 3016296			10-381550-22 NN01446608	MTH 30-Jun-1997 HRS 15654		O/C	0		
741010 E2 LOWER	IGNITION EXCITER 3016296			10-381550-2A SN-UNKNOWN	MTH 13-Jul-2011 HRS 17953.5 LDG 21983		O/C	0 3336.3 0		
742010 E1 OUTBOARD	IGNITER PLUG			FHE-246-4 SN-UNKNOWN	MTH 17-Jun-2003 HRS 17624		O/C	0		
742010 E2 OUTBOARD	IGNITER PLUG	UVA		FHE-246-4 SN-UNKNOWN	MTH 21-Jul-2011 HRS 17953.5 LDG 21983		O/C	0 0 0		
742020 E1 INBOARD	IGNITER PLUG 3030595			FHE-246-4 SN-UNKNOWN	MTH 17-Jun-2003 HRS 17624		O/C	0		
742020 E2 INBOARD	IGNITER PLUG 3030595	UVA		FHE-246-4 SN-UNKNOWN	MTH 21-Jul-2011 HRS 17953.5 LDG 21983		O/C	0 0 0		
742030 E1 SHORT	IGNITER LEAD			53067-21 SN-UNKNOWN	MTH 30-Jun-1997 HRS 15654		O/C	0		
742030 E2 SHORT	IGNITER LEAD			PN SN-UNKNOWN	MTH 08-May-1979		O/C	0		
742040 E1 LONG	IGNITER LEAD 3027939			10-395428-1 SN-UNKNOWN	MTH 30-Jun-1997 HRS 15654		O/C	0		
742040 E2 LONG	IGNITER LEAD			PN SN-UNKNOWN	MTH 08-May-1979		O/C	0		
750001 LEFT INBOARD	BLEED AIR FLEX JOINT COUPLING 9912025-4		*CF	31A402 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
750001 LEFT OUTBOARD	BLEED AIR FLEX JOINT COUPLING 9912025-4		*CF	31A402 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
750001 RIGHT INBOARD	BLEED AIR FLEX JOINT COUPLING 9912025-2		*CF	31A402 SN-UNKNOWN	MTH 31-Oct-1980		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **JALAIR LP**  
 Aircraft Model: **501 - MODEL 501**  
 Aircraft Serial: **501-0169** Unit: **0566** Reg No: **C-GFEE**  
 Airworthiness: **31-Oct-1980**  
 Print Date: **22-Aug-2012 7:10PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>17995.4</b>	<b>22037</b>	<b>18-Aug-2012</b>	<b>.02</b>
<b>ENG 1</b>	<b>8791.4</b>	<b>9226</b>	<b>18-Aug-2012</b>	<b>.03</b>
<b>ENG 2</b>	<b>7046.1</b>	<b>6912</b>	<b>18-Aug-2012</b>	<b>.03</b>

### Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
750001 RIGHT OUTBOARD	BLEED AIR FLEX JOINT COUPLING 9912025-2	*CF		31A402 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
750010 E1	LOW PRESSURE COMPRESSOR ANTI-ICING 3029591			SOLENOID VALVE 3244758-1 A57860	MTH 30-Jun-1997 HRS 15654		O/C	0		
750010 E2	LOW PRESSURE COMPRESSOR ANTI-ICING			SOLENOID VALVE PN SN-UNKNOWN	MTH 08-May-1979		O/C	0		
751002 E1	BA SOL VALVE-STATORS --			KW15632 2136	MTH 30-Jun-1997 HRS 15654		O/C	0		
761001	ENGINE CONTROL QUADRANT ASSEMBLY *CF			5565810-1 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
761002 NO. 1 ENGINE	MAIN THROTTLE CONTROL CABLE *CF			411D0315-3 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
761002 NO. 2 ENGINE	MAIN THROTTLE CONTROL CABLE *CF			411D0315-3 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
761003 NO. 1 ENGINE	NACELLE THROTTLE CONTROL CABLE *CF			7-42346-1 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
761004 NO. 2 ENGINE	NACELLE THROTTLE CONTROL CABLE *CF			7-42346-2 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
761005	DEPLOY INTERLOCK SOLENOID ASSEMBLY 9912110-1	*CF		U-183238-001 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
771001 LEFT BOTTOM	N2 TACH GENERATOR *CF			22A623 2192	MTH 31-Oct-1980		O/C			
771001 LEFT TOP	N1 TACH GENERATOR 9912034-1			AG34 36039	MTH 19-Jun-1989 HRS 9664		O/C	0		
771001 RIGHT BOTTOM	N2 TACH GENERATOR *CF			22A623 2552	MTH 31-Oct-1980		O/C			
771001 RIGHT TOP	N1 TACH GENERATOR *CF			22A623 2502	MTH 31-Oct-1980		O/C			
771002	N2 (TURBINE) INDICATOR 9912147-6			VSDL-OC410B 204B	MTH 30-May-2000 HRS 16712		O/C	61		
771003	N1 (FAN) INDICATOR 9912147-20			VSDL-OC410R 58	MTH 30-May-2000 HRS 16712		O/C	732		
772001	ITT INDICATOR 9912147-4			VSDL-OC419A 135CAEFGK	MTH 26-Aug-1985 HRS 5700		O/C	0		
781001 NO. 1 ENGINE	EXHAUST NOZZLE CONE *CF			5555020-41 SN-UNKNOWN	MTH 31-Oct-1980		O/C			
781001 NO. 2 ENGINE	EXHAUST NOZZLE CONE *CF			5555020-41 SN-UNKNOWN	MTH 31-Oct-1980		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **JALAIR LP**  
 Aircraft Model: **501 - MODEL 501**  
 Aircraft Serial: **501-0169** Unit: **0566** Reg No: **C-GFEE**  
 Airworthiness: **31-Oct-1980**  
 Print Date: **22-Aug-2012 7:10PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>17995.4</b>	<b>22037</b>	<b>18-Aug-2012</b>	<b>.02</b>
<b>ENG 1</b>	<b>8791.4</b>	<b>9226</b>	<b>18-Aug-2012</b>	<b>.03</b>
<b>ENG 2</b>	<b>7046.1</b>	<b>6912</b>	<b>18-Aug-2012</b>	<b>.03</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
783001 LEFT	THRUST REVERSER ASSEMBLY	*CF		202-0000-1 0328	MTH 31-Oct-1980		O/C			
783001 RIGHT	THRUST REVERSER ASSEMBLY			202-0000-3 564666-1	MTH 09-Apr-1986 HRS 6402 LDG 8063		O/C	0		
783002 LEFT	THRUST REVERSER CONTROL VALVE	*CF		65680 119	MTH 31-Oct-1980		O/C			
783002 RIGHT	THRUST REVERSER CONTROL VALVE	*CF		65680 123	MTH 31-Oct-1980		O/C			
783003 LEFT	THREE-WAY VALVE	*CF		13027-4 591	MTH 31-Oct-1980		O/C			
783003 RIGHT	THREE-WAY VALVE	*CF		13027-4 669	MTH 31-Oct-1980		O/C			
783005 LEFT UPPER	THRUST REVERSER DOOR	*CF		202-0001-1 0303	MTH 31-Oct-1980		O/C			
783005 RIGHT UPPER	THRUST REVERSER DOOR	*CF		9912110-1 202-0001-2 0340	MTH 31-Oct-1980		O/C			
783006 LEFT LOWER	THRUST REVERSER DOOR	*CF		202-0002-1 0320	MTH 31-Oct-1980		O/C			
783006 RIGHT LOWER	THRUST REVERSER DOOR	*CF		202-0002-2 0340	MTH 31-Oct-1980		O/C			
783007 LEFT	THRUST REVERSER MECH ASSEMBLY	*CF		202-0004-1 0651	MTH 31-Oct-1980		O/C			
783007 RIGHT	THRUST REVERSER MECH ASSEMBLY	*CF		202-0004-1 0684	MTH 31-Oct-1980		O/C			
783008 LEFT	THRUST REVERSER MECH ASSEMBLY	*CF		202-0004-3 0605	MTH 31-Oct-1980		O/C			
783008 RIGHT	THRUST REVERSER MECH ASSEMBLY	*CF		9912110-1 202-0004-5 0640	MTH 31-Oct-1980		O/C			
783009 LEFT	THRUST REVERSER FAN DUCT	*CF		202-0012-1 0649	MTH 31-Oct-1980		O/C			
783009 RIGHT	THRUST REVERSER FAN DUCT	*CF		202-0012-1 0682	MTH 31-Oct-1980		O/C			
783010 LEFT INBOARD	THRUST REVERSER ACTUATOR			7U7555 1059	MTH 15-Mar-1990 HRS 10265 LDG 12960		O/C	0		
783010 LEFT OUTBOARD	THRUST REVERSER ACTUATOR			7U7555 SN-UNKNOWN	MTH 18-Sep-1987 HRS 8197 LDG 10405		O/C	0		
783010 RIGHT INBOARD	THRUST REVERSER ACTUATOR			62270 597	MTH 17-Dec-1987 HRS 8427 LDG 10686		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **JALAIR LP**

Aircraft Model: **501 - MODEL 501**

Aircraft Serial: **501-0169** Unit: **0566** Reg No: **C-GFEE**

Airworthiness: **31-Oct-1980**

Print Date: **22-Aug-2012 7:10PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>17995.4</b>	<b>22037</b>	<b>18-Aug-2012</b>	<b>.02</b>
<b>ENG 1</b>	<b>8791.4</b>	<b>9226</b>	<b>18-Aug-2012</b>	<b>.03</b>
<b>ENG 2</b>	<b>7046.1</b>	<b>6912</b>	<b>18-Aug-2012</b>	<b>.03</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
783010 RIGHT OUTBOARD	THRUST REVERSER ACTUATOR 9912110-1			7U7555 597	MTH 22-Jan-1986 HRS 6178 LDG 7762		O/C			0
793001	OIL TEMPERATURE INDICATOR 9912147-1			VSDL-OC219A 13972BA	MTH 19-Jun-1993 HRS 12955		O/C			0
793002 LEFT ENGINE	OIL TEMPERATURE TRANSMITTER *CF			MS28034-3 88360	MTH 31-Oct-1980		O/C			
793002 RIGHT ENGINE	OIL TEMPERATURE TRANSMITTER *CF			MS28034-3 87159	MTH 31-Oct-1980		O/C			
793003	OIL PRESSURE INDICATOR 9912147-3			VSDL-OC204A 34	MTH 15-Aug-1989 HRS 9695		O/C			0
793004 LEFT ENGINE	OIL PRESSURE TRANSMITTER 9912164-1			123479 36947	MTH 30-Jan-1990 HRS 10191		O/C			0
793004 RIGHT ENGINE	OIL PRESSURE TRANSMITTER 9912164-1			123479 30013	MTH 08-Feb-1990 HRS 10209		O/C			2268
793006 LEFT ENGINE	LOW OIL PRESSURE SWITCH 9912178-2			1103P89-1 242	MTH 18-Aug-1986 HRS 6775		O/C			0
792003 E1	OIL FILTER			3015330 SN-UNKNOWN	MTH 30-Jun-1997 HRS 15654		O/C			0
792003 E2	OIL FILTER	UVA		3015330 SN-UNKNOWN	MTH 21-Jul-2011 HRS 17953.5 LDG 21983		O/C			0 0 0
832001 E1	MAIN GEARBOX ASSEMBLY			3018390 SN-UNKNOWN	MTH 30-Jun-1997 HRS 15654		O/C			0
832001 E2	MAIN GEARBOX ASSEMBLY			3018390 SN-UNKNOWN	MTH 13-Jul-2011 HRS 17953.5 LDG 21983		O/C			0 3336.3 0



# CESCOM 10 - Aircraft Status Report

Owner: **JALAIR LP**  
 Aircraft Model: **501 - MODEL 501**  
 Aircraft Serial: **501-0169** Unit: **0566** Reg No: **C-GFEE**  
 Airworthiness: **31-Oct-1980**  
 Print Date: **22-Aug-2012 7:10PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>17995.4</b>	<b>22037</b>	<b>18-Aug-2012</b>	<b>.02</b>
<b>ENG 1</b>	<b>8791.4</b>	<b>9226</b>	<b>18-Aug-2012</b>	<b>.03</b>
<b>ENG 2</b>	<b>7046.1</b>	<b>6912</b>	<b>18-Aug-2012</b>	<b>.03</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 500-11-02 <i>11SL-2</i>	PLACARDS AND MARKINGS - DATA PLATE RELOCATION OPTIONAL			MTH			A/R			
<b>MOC :</b> - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SL CIL-99-01	USE OF CORROSION INHIBITING COMPOUNDS INFORMATIONAL						-			
<b>MOC :</b>										
SL CIL-99-02	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS RECOMMENDED			MTH	12-Jul-2012		-			Complete
					HRS	17992.7				
					LDG	22033				
<b>MOC :</b> COMPLIED WITH - FLIGHT CREW HAS BEEN BRIEFED ON CIL-99-02 TO AVOID OPERATIONS ON RUNWAYS TREATED WITH RDI FLUIDS AND THAT AIRCRAFT WASHING IS RECOMMENDED FOLLOWING EXPOSURE TO RDI										
SL CIL-20-01	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL						-			
<b>MOC :</b>										
SL 500-20-02 R27	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL INFORMATIONAL						A/R			
<b>MOC :</b>										
SB 500-21-08 <i>21SB-8</i>	SUPPLEMENTAL FLIGHT COMPARTMENT VENTILATION SYSTEM INSTALLATION OPTIONAL			MTH			A/R			
<b>MOC :</b> - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB 500-21-15 <i>21SB-15</i>	FREON AIR CONDITIONING SYSTEM INSTALLATION OPTIONAL			MTH			A/R			
<b>MOC :</b> - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB 500-21-16 <i>21SB-16</i>	AIRCONDITIONING - COCKPIT AIR DISTRIBUTION - ADD SUPPLEMENTARY AIR OUTLETS ON SIDE CONSOLES OPTIONAL			MTH			A/R			
<b>MOC :</b> - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB 500-21-19 <i>21SB-19</i>	AIR CONDITIONING - NOSE GEAR DOORS MODIFICATION OPTIONAL			MTH			A/R			
<b>MOC :</b> - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB 500-21-20 <i>21SB-20</i>	CABIN VENTILATION MOTOR REPLACEMENT SWF OPTIONAL			MTH	10-Aug-1989		A/R			Complete
					HRS	9678				
<b>MOC :</b> COMPLIED WITH										
SB 500-21-21 <i>21SB-21</i>	OUTFLOW VALVE REPLACEMENT			MTH	17-Nov-1992		A/R			Complete
					HRS	12424				
<b>MOC :</b> COMPLIED WITH										
SB 500-21-22 <i>21SB-22</i>	AIR CONDITIONING - ALTERNATE FLOW CONTROL VALVE INSTALLATION OPTIONAL			MTH	22-Sep-1994		A/R			Complete
					HRS	13803				
<b>MOC :</b> COMPLIED WITH										
SB 500-21-23 <i>21SB-23</i>	ADDITIONAL OUTFLOW VALVE REPLACEMENTS MANDATORY			MTH	15-Aug-1995		-			Complete
					HRS	14446				
<b>MOC :</b> COMPLIED WITH - NOT APPLICABLE BY COMPONENT SERIAL NUMBER.										



# CESCOM 10 - Aircraft Status Report

Owner: **JALAIR LP**  
 Aircraft Model: **501 - MODEL 501**  
 Aircraft Serial: **501-0169** Unit: **0566** Reg No: **C-GFEE**  
 Airworthiness: **31-Oct-1980**  
 Print Date: **22-Aug-2012 7:10PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>17995.4</b>	<b>22037</b>	<b>18-Aug-2012</b>	<b>.02</b>
<b>ENG 1</b>	<b>8791.4</b>	<b>9226</b>	<b>18-Aug-2012</b>	<b>.03</b>
<b>ENG 2</b>	<b>7046.1</b>	<b>6912</b>	<b>18-Aug-2012</b>	<b>.03</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
<i>SB 500-21-24</i> <i>21SB-24</i>	AIR CONDITIONING - CABIN FAN AND DEFOG BLOWER WIRING IMPROVEMENT DISCRETIONARY			MTH			A/R			
<b>MOC :</b> - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
<i>SB 500-21-25</i>	AIR CONDITIONING - TEMPERATURE CONTROLLER IMPROVEMENT OPTIONAL						A/R			
<b>MOC :</b>										
<i>SL CIL-21-01</i>	COMPRESSOR MOTOR BRUSH LIFE LIMIT INFORMATIONAL						-			
<b>MOC :</b>										
<i>SL 500-21-12</i> <i>21SL-12</i>	DEACTIVATION OF COOLING BLOWER THERMAL SWITCHES RECOMMENDED			MTH			A/R			
<b>MOC :</b> - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
<i>SL 500-21-15</i> <i>21SL-15</i>	ENGINE BLEED AIR CHECK VALVES YTS		OPTIONAL	MTH	21-Jul-1982 HRS 1033		A/R			Complete
<b>MOC :</b> COMPLIED WITH										
<i>SL 500-21-20</i> <i>21SL-20</i>	AIR CONDITIONING - COMPRESSOR DRIVE MOTOR BRUSH INSPECTION/REPLACEMENT (FORT WORTH AIRWORKS INC. - ZEPHYR AIR CONDITIONING) YHU		RECOMMENDED	MTH	11-Apr-2006 HRS 17721		A/R			N/A
<b>MOC :</b> NOT APPLICABLE - NOT APPLICABLE										
<i>SB 500-22-07</i> <i>22SB-7</i>	AUTO FLIGHT - SINGLE AND DUAL ACCELEROMETER INSTALLATION OPTIONAL			MTH			A/R			
<b>MOC :</b> - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
<i>SB 500-22-09</i> <i>22SB-9</i>	AUTO FLIGHT - FLIGHT DIRECTOR COMPUTER VERTICAL SPEED HOLD WIRING MODIFICATION OPTIONAL			MTH			A/R			
<b>MOC :</b> - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
<i>SB 500-23-10</i> <i>23SB-10</i>	COMMUNICATION - FLITEPHONE III INSTALLATION OPTIONAL			MTH			A/R			
<b>MOC :</b> - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
<i>SB 500-23-15</i> <i>23SB-15</i>	STATIC DISCHARGE IMPROVEMENT OPTIONAL			MTH			A/R			
<b>MOC :</b> - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
<i>SB 500-23-16</i> <i>23SB-16</i>	COMMUNICATIONS - STATIC WICK REPLACEMENT *CF		OPTIONAL	MTH			A/R			
<b>MOC :</b> - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
<i>SB 500-23-17 R1</i> <i>23SB-17 : REV1</i>	COLLINS 8.33 KHZ COMMUNICATION RADIO INSTALLATION OPTIONAL			MTH			A/R			
<b>MOC :</b> - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
<i>SB 500-23-18 R1</i> <i>23SB-18 : REV1</i>	VLF NOISE FILTER CAPACITOR REMOVAL/REPLACEMENT MANDATORY			MTH	13-Jun-2000 HRS 16733		-			Complete
<b>MOC :</b> COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
<i>SL 500-23-11</i> <i>23SL-11</i>	AVTECH AUDIO AMP - INSTALLATION OF INCREASED VOLTAGE CAPACITORS OPTIONAL			MTH			A/R			
<b>MOC :</b> - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										



# CESCOM 10 - Aircraft Status Report

Owner: **JALAIR LP**  
 Aircraft Model: **501 - MODEL 501**  
 Aircraft Serial: **501-0169** Unit: **0566** Reg No: **C-GFEE**  
 Airworthiness: **31-Oct-1980**  
 Print Date: **22-Aug-2012 7:10PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>17995.4</b>	<b>22037</b>	<b>18-Aug-2012</b>	<b>.02</b>
<b>ENG 1</b>	<b>8791.4</b>	<b>9226</b>	<b>18-Aug-2012</b>	<b>.03</b>
<b>ENG 2</b>	<b>7046.1</b>	<b>6912</b>	<b>18-Aug-2012</b>	<b>.03</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 500-23-14 23SL-14	COMMUNICATION - 66 TRA MICROPHONE CORD REPLACEMENT PROGRAM	YHU		RECOMMENDED	MTH 11-Apr-2006 HRS 17721		A/R			N/A
<b>MOC : NOT APPLICABLE - NOT APPLICABLE</b>										
SL 500-23-15 23SL-15	COMMUNICATION - STATIC DISCHARGE WICK MODIFICATION			OPTIONAL	MTH 28-Aug-1989 HRS 9754		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 500-24-05 24SB-5	ELECTRICAL - BATTERY TEMPERATURE MONITOR GAUGE SYSTEM			OPTIONAL	MTH 15-Aug-1971		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 500-24-12 R2 24SB-12 : REV2	BATTERY AND EXTERNAL POWER BOX RECEPTACLE GROUND IMPROVEMENT	YTS		MANDATORY	MTH 23-Dec-1981 HRS 390		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 500-24-12 24SB-12	BATTERY AND EXTERNAL POWER BOX RECEPTACLE GROUND IMPROVEMENT	ICT		MANDATORY	MTH 12-Nov-1980 HRS 17		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 500-24-13 24SB-13	300 VA INVERTER WATER SHIELD INSTALLATION			OPTIONAL	MTH		A/R			
<b>MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME</b>										
SB 500-24-16 R1 24SB-16 : REV1	ELECTRICAL POWER - CONTROL WHEEL ELECTRICAL CABLE REPLACEMENT			OPTIONAL	MTH 09-May-2008 HRS 17851		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 500-24-17 R2 24SB-17 : REV2	GENERATOR CONTROL UNIT START CIRCUIT MODIFICATION			RECOMMENDED	MTH		A/R			
<b>MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME</b>										
SB 500-24-18 24SB-18	ELECTRICAL POWER - WING TIP WIRE BUNDLE PROTECTIVE COVER INSTALLATION	YHU		RECOMMENDED	MTH 11-Apr-2006 HRS 17721		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 500-24-20 R1 24SB-20 : REV1	ELECTRICAL POWER - OVERVOLTAGE MONITOR SYSTEM INSTALLATION			OPTIONAL	MTH		A/R			
<b>MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME</b>										
SB 500-24-21 24SB-21	ELECTRICAL POWER - BATTERY DISCONNECT RELAY ACCESS IMPROVEMENT			OPTIONAL	MTH		A/R			
<b>MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME</b>										
SB 500-24-22 24SB-22	ELECTRICAL POWER - SEALED LEAD ACID BATTERY INSTALLATION			OPTIONAL	MTH		A/R			
<b>MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME</b>										
SB 500-24-23	ELECTRICAL POWER - MAGNETIC CIRCUIT BREAKER MODIFICATION			OPTIONAL			A/R			
<b>MOC :</b>										





# CESCOM 10 - Aircraft Status Report

Owner: **JALAIR LP**  
 Aircraft Model: **501 - MODEL 501**  
 Aircraft Serial: **501-0169** Unit: **0566** Reg No: **C-GFEE**  
 Airworthiness: **31-Oct-1980**  
 Print Date: **22-Aug-2012 7:10PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>17995.4</b>	<b>22037</b>	<b>18-Aug-2012</b>	<b>.02</b>
<b>ENG 1</b>	<b>8791.4</b>	<b>9226</b>	<b>18-Aug-2012</b>	<b>.03</b>
<b>ENG 2</b>	<b>7046.1</b>	<b>6912</b>	<b>18-Aug-2012</b>	<b>.03</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 500-24-13 24SL-13	300 VA INVTR SHIELD				MTH		A/R			
<b>MOC :</b> - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB 500-25-17 25SB-17	AFT PORTABLE SEAT INSTALLATION			OPTIONAL	MTH 15-Aug-1971		A/R			Complete
<b>MOC :</b> COMPLIED WITH										
SB 500-25-20 25SB-20	EQUIPMENT/FURNISHINGS - STRETCHER INSTALLATION			OPTIONAL	MTH		A/R			
<b>MOC :</b> - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB 500-25-22 25SB-22	THREE PLACE SIDE FACING COUCH INSTALLATION			OPTIONAL	MTH		A/R			
<b>MOC :</b> - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB 500-25-28 R1 25SB-28 : REV1	FOUR-POINT RESTRAINT SYSTEM INSTALLATION			OPTIONAL	MTH		A/R			
<b>MOC :</b> - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB 500-25-31 R2 25SB-31 : REV2	EQUIPMENT/FURNISHINGS - ARTEX C406-2 THREE-FREQUENCY EMERGENCY LOCATOR TRANSMITTER (ELT)			OPTIONAL	MTH 09-May-2008 HRS 17851		A/R			Complete
<b>MOC :</b> COMPLIED WITH										
SB 500-25-31 R3	ARTEX C406-2 THREE-FREQUENCY EMERGENCY LOCATOR TRANSMITTER (ELT)			OPTIONAL			A/R			
<b>MOC :</b>										
SL 500-25-03 25SL-3	INSPECTION/MODIFICATION OF PERSONAL FLOTATION DEVICES			MANDATORY	MTH HRS		600			
NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
<b>MOC :</b>										
SL 500-25-05 25SL-5	SWITLIK INFLATABLE LIFE PRESERVER INSPECTION			INFORMATIONAL	MTH 05-May-1989 HRS 9543		A/R			Complete
<b>MOC :</b> COMPLIED WITH - NOT APPLICABLE BY DATE OF MANUFACTURE										
SL 500-25-08 25SL-08	TRANSMITTAL OF EASTERN AERO MARINE SERVICE BULLETIN SBV-25-2, EQUIPMENT/FURNISHINGS - LIFE PRESERVERS AND INDIVIDUAL FLOTATION DEVICES REPLACEMENT OF CO2 INFLATOR	YHU		MANDATORY	MTH 11-Apr-2006 HRS 17721		-			N/A
<b>MOC :</b> NOT APPLICABLE - NOT APPLICABLE										
SL 500-25-09 25SL-09	EQUIPMENT/FURNISHINGS - GLARESHIELD ATTACHMENT SCREW(S) INSPECTION/REPLACEMENT			RECOMMENDED	MTH 13-Jun-2000 HRS 16733		A/R			Complete
<b>MOC :</b> COMPLIED WITH										
SB 500-26-02 R1 26SB-02 : REV1	FIRE PROTECTION - FIRE BOTTLE WIRE IDENTIFICATION SLEEVE INSTALLATION			MANDATORY	MTH 11-Apr-2006 HRS 17720		A/R			Complete
<b>MOC :</b> COMPLIED WITH										
ASL 500-26-02 26ASL02	FIRE PROTECTION - TRANSMITTAL OF MEGGITT SAFETY SYSTEMS SERVICE BULLETIN 26-36 - THERMISTORS DETECTORS			MANDATORY	MTH 18-Oct-2007 HRS 17809		A/R			N/A
<b>MOC :</b> NOT APPLICABLE - NOT APPLICABLE-EQUIPMENT NOT INSTALLED										



# CESCOM 10 - Aircraft Status Report

Owner: **JALAIR LP**  
 Aircraft Model: **501 - MODEL 501**  
 Aircraft Serial: **501-0169** Unit: **0566** Reg No: **C-GFEE**  
 Airworthiness: **31-Oct-1980**  
 Print Date: **22-Aug-2012 7:10PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>17995.4</b>	<b>22037</b>	<b>18-Aug-2012</b>	<b>.02</b>
<b>ENG 1</b>	<b>8791.4</b>	<b>9226</b>	<b>18-Aug-2012</b>	<b>.03</b>
<b>ENG 2</b>	<b>7046.1</b>	<b>6912</b>	<b>18-Aug-2012</b>	<b>.03</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 500-26-01 26SL-1	ENGINE FIRE WARNING TRAY			RECOMMENDED	MTH 30-Jun-1986 HRS 6703		A/R			Complete
	MOC : COMPLIED WITH									
SB 500-27-09 27SB-9	SPEED BRAKE CONTROL SWITCH SPARE REPLACEMENT	YTS		OPTIONAL	MTH 20-Jul-1984 HRS 4027		A/R			Complete
	MOC : COMPLIED WITH									
SB 500-27-10 27SB-10	FLIGHT CONTROLS - AILERON ACTUATOR CABLE GUARD MODIFICATION	YTS		RECOMMENDED	MTH 01-Mar-1984 HRS 3399		A/R			Complete
	MOC : COMPLIED WITH									
SB 500-27-11 27SB-11	FLIGHT CONTROLS - FLAP BEARING AND ROLLER REPLACEMENT			OPTIONAL	MTH		A/R			
	MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SB 500-27-12 27SB-12	FLIGHT CONTROLS - RIGHT THROTTLE LEVER LOCKING CAM REPLACEMENT			MANDATORY	MTH 07-Nov-1984 HRS 4506		A/R			Complete
	MOC : COMPLIED WITH									
SB 500-27-13 27SB-13	FLIGHT CONTROLS - SPEED BRAKE PUSH ROD REPLACEMENT			OPTIONAL	MTH		A/R			
	MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SB 500-27-14 27SB-14	FLIGHT CONTROLS - FLAP MOTOR CONNECTOR INSTALLATION	*CF		OPTIONAL	MTH		A/R			
	MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SB 500-27-15 R1 27SB-15 : REV1	FLAP GEARBOX REPLACEMENT	YHU		RECOMMENDED	MTH 11-Apr-2006 HRS 17721		-			N/A
	MOC : NOT APPLICABLE - INTENT ACCOMPLISHED DURING PREVIOUS MAINTENANCE OR THROUGH ALTERNATE METHOD OF COMPLIANCE.									
SB 500-27-16 27SB-16	ELEVATOR ELECTRIC TRIM ACTUATOR REPLACEMENT			RECOMMENDED	MTH 21-Jun-2005 HRS 17697		-			N/A
	MOC : NOT APPLICABLE - NOT APPLICABLE									
SB 500-27-19 27SB-19	FLIGHT CONTROLS - TRIM TAB ACTUATOR GREASE FITTING INSTALLATION			OPTIONAL	MTH		A/R			
	MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SL 500-27-06 27SL-6	INSPECTION OF ELEVATOR AND RUDDER TRIM SYSTEM	YTS		MANDATORY	MTH 29-Jun-1983 HRS 2398		A/R			Complete
	MOC : COMPLIED WITH									
SL 500-27-11 27SL-11	FLIGHT CONTROLS - RUDDER PEDAL SUPPORT INSPECTION			RECOMMENDED	MTH 12-Sep-2008 HRS 17864		A/R			Complete
	MOC : COMPLIED WITH - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SB 500-28-07 28SB-7	FUEL - MOTIVE FLOW FUEL PRESSURE SWITCH REMOVAL			OPTIONAL	MTH		A/R			
	MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SB 500-28-09 28SB-09	FUEL - IMPROVED FUEL CROSSFEED SELECT KNOB AVAILABILITY			OPTIONAL	MTH		A/R			
	MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									



# CESCOM 10 - Aircraft Status Report

Owner: **JALAIR LP**  
 Aircraft Model: **501 - MODEL 501**  
 Aircraft Serial: **501-0169** Unit: **0566** Reg No: **C-GFEE**  
 Airworthiness: **31-Oct-1980**  
 Print Date: **22-Aug-2012 7:10PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>17995.4</b>	<b>22037</b>	<b>18-Aug-2012</b>	<b>.02</b>
<b>ENG 1</b>	<b>8791.4</b>	<b>9226</b>	<b>18-Aug-2012</b>	<b>.03</b>
<b>ENG 2</b>	<b>7046.1</b>	<b>6912</b>	<b>18-Aug-2012</b>	<b>.03</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 500-28-10 28SB-10	WING FUEL CELL FOAM BLOCK REMOVAL			OPTIONAL	MTH 15-Jun-1996 HRS 15055		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 500-28-11 28SB-11 : 500	FUEL - TANK BRACKET AND CLAMP INSTALLATION/INSPECTION	YHU		RECOMMENDED	MTH 11-Apr-2006 HRS 17721		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 500-28-12 28SB-12	WING FUEL BOOST PUMP WIRE ROUTING IMPROVEMENT	YSC		MANDATORY	MTH 19-Feb-2005 HRS 17676		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
ASL 500-28-09 R1 28SLA09 : REV1	FUEL - TRANSMITTAL OF PARKER HANNIFIN CORPORATION - AIRBORNE AIR & FUEL PRODUCTS SERVICE LETTER NO. 41, RAPCO FLEET SUPPORT INC. OVERHAUL OF AIRBORNE FUEL PUMPS			MANDATORY	MTH 08-Jul-1996 HRS 15109		A/R			Complete
<b>MOC : COMPLIED WITH - NOT APPLICABLE</b>										
SL 500-28-08 R1 28SL-08 : REV1	FUEL-FUEL CELL INSPECTION REQUIREMENTS			MANDATORY	MTH 11-Apr-2006 HRS 17720		A/R			Complete
<b>MOC : COMPLIED WITH - INTENT ACCOMPLISHED DURING PREVIOUS MAINTENANCE OR THROUGH ALTERNATE METHOD OF COMPLIANCE.</b>										
SL 500-29-04 29SL-4	PORTABLE HYDRAULIC SERVICE UNIT (MINI-MULE)			RECOMMENDED	MTH		A/R			
<b>MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME</b>										
SL 500-30-06 30SL-6	EROSION SHOES FOR WING TIP PYLON LEADING EDGE, HORIZONTAL STABILIZER/VERTICAL FIN TIPS			OPTIONAL	MTH		A/R			
<b>MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME</b>										
SB 500-32-27 32SB-27	LANDING GEAR - GRAVEL RUNWAY SYSTEM INSTALLATION	YTS		OPTIONAL	MTH 08-Apr-1982 HRS 698		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 500-32-28 32SB-28	ANTI-SKID BRAKE SYSTEM INSTALLATION			OPTIONAL	MTH		A/R			
<b>MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME</b>										
SB 500-32-37 32SB-37	LANDING GEAR - MAIN GEAR ACTUATOR ATTACH STUD REPLACEMENT	YTS		MANDATORY	MTH 11-Nov-1983 HRS 2998		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 500-32-38 R7 32SB-38 : REV7	BFGOODRICH BRAKES AND WHEELS INSTALLATION			OPTIONAL	MTH		A/R			
<b>MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME</b>										
SB 500-32-39 32SB-39	LANDING GEAR - NOSE GEAR STEERING BUNGEE SPRING REPLACEMENT	YHU		RECOMMENDED	MTH 11-Apr-2006 HRS 17721		A/R			N/A
<b>MOC : NOT APPLICABLE - NOT APPLICABLE</b>										
SB 500-32-41 32SB-41	LANDING GEAR - BFGOODRICH BRAKE BLEEDER BLOCK INSTALLATION AND HOSE REPLACEMENT			OPTIONAL	MTH		A/R			
<b>MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME</b>										
SB 500-32-42 32SB-42	LANDING GEAR - MLG WHEEL WELL AFT SPAR BOX HYDRAULIC/PNEUMATIC LINES GROMMET REPLACEMENT			RECOMMENDED	MTH 11-Mar-1993 HRS 12655		A/R			Complete
<b>MOC : COMPLIED WITH</b>										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **JALAIR LP**  
 Aircraft Model: **501 - MODEL 501**  
 Aircraft Serial: **501-0169** Unit: **0566** Reg No: **C-GFEE**  
 Airworthiness: **31-Oct-1980**  
 Print Date: **22-Aug-2012 7:10PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>17995.4</b>	<b>22037</b>	<b>18-Aug-2012</b>	<b>.02</b>
<b>ENG 1</b>	<b>8791.4</b>	<b>9226</b>	<b>18-Aug-2012</b>	<b>.03</b>
<b>ENG 2</b>	<b>7046.1</b>	<b>6912</b>	<b>18-Aug-2012</b>	<b>.03</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 500-32-43 <i>32SB-43</i>	MAIN LANDING GEAR SIDE BRACE STUD INSPECTION/REPLACEMENT			RECOMMENDED	MTH 06-Oct-1994 HRS 13822		-			Complete
	<b>MOC : COMPLIED WITH</b>									
SB 500-32-45 <i>32SB-45</i>	POWER BRAKE HYDRAULIC PUMP SCREW REPLACEMENT	YHU		RECOMMENDED	MTH 11-Apr-2006 HRS 17721		-			N/A
	<b>MOC : NOT APPLICABLE - NOT APPLICABLE</b>									
SB 500-32-47 R3 <i>32SB-47 : REV3</i>	LANDING GEAR - TRANSMITTAL OF BFGOODRICH SERVICE BULLETIN 2-1530-32-2, LANDING GEAR - BRAKE ASSEMBLY POSSIBLE CRACKED STATORS			MANDATORY	MTH 21-Jun-2005 HRS 17697		A/R			N/A
	<b>MOC : NOT APPLICABLE - NOT APPLICABLE-EQUIPMENT NOT INSTALLED</b>									
SB 500-32-48 R3 <i>32SB-48 : REV3</i>	LANDING GEAR - TRANSMITTAL OF BFGOODRICH SERVICE BULLETIN 2-1528-32-2, LANDING GEAR - BRAKE ASSEMBLY POSSIBLE CRACKED STATORS DISKS			MANDATORY	MTH 21-Jun-2005 HRS 17697		A/R			N/A
	<b>MOC : NOT APPLICABLE - NOT APPLICABLE-EQUIPMENT NOT INSTALLED</b>									
ASL 500-32-34 <i>32SLA34</i>	MAIN GEAR ACTUATOR TO STRUT ATTACH STUD INSPECTION	YTS		MANDATORY	MTH 14-Oct-1983 HRS 2909		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									
ASL 500-32-62 <i>32SLA62</i>	LANDING GEAR - MAIN LANDING GEAR ACTUATOR STUD(S) INSPECTION/REPLACEMENT			MANDATORY	MTH 30-Apr-1993 HRS 12815		A/R			Complete
	<b>MOC : COMPLIED WITH - NOT APPLICABLE</b>									
SL 500-32-28 <i>32SL-28</i>	REPLACEMENT OF WESTERN HYDRAULIC MAIN AND NOSE GEAR ACTUATORS	YHU		RECOMMENDED	MTH 11-Apr-2006 HRS 17721		A/R			N/A
	<b>MOC : NOT APPLICABLE - NOT APPLICABLE BY TYPE MANUFACTURER</b>									
SL 500-32-35 <i>32SL-35</i>	AIR STORAGE BOTTLE			RECOMMENDED	MTH 13-May-1984 HRS 3704		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									
SL 500-32-38 <i>32SL-38</i>	NOSE GEAR STEERING LOWER JOINT BEARING INSPECTION			RECOMMENDED	MTH 25-Sep-1987 HRS 8197		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									
SL 500-32-41 <i>32SL-41</i>	LANDING GEAR - UPLOCK ACTUATOR HYDRAULIC LINE INSPECTION			RECOMMENDED	MTH 17-Apr-1989 HRS 9473		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									
SL 500-32-42 <i>32SL-42</i>	LANDING GEAR - MAIN LANDING GEAR AXLE INTERNAL CORROSION INSPECTION			RECOMMENDED	MTH 05-May-1989 HRS 9543		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									
SL 500-32-48 <i>32SL-48</i>	LANDING GEAR - LANDING GEAR EMERGENCY EXTENSION CONTROL ASSEMBLY PIN INSPECTION			RECOMMENDED	MTH 17-Aug-1990 HRS 10578		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									
SL 500-32-53 <i>32SL-53</i>	LANDING GEAR - NOSE LANDING GEAR UPLOCK LINE INSPECTION			RECOMMENDED	MTH 18-Jun-1991 HRS 11174		A/R			Complete
	<b>MOC : COMPLIED WITH</b>									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **JALAIR LP**  
 Aircraft Model: **501 - MODEL 501**  
 Aircraft Serial: **501-0169** Unit: **0566** Reg No: **C-GFEE**  
 Airworthiness: **31-Oct-1980**  
 Print Date: **22-Aug-2012 7:10PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>17995.4</b>	<b>22037</b>	<b>18-Aug-2012</b>	<b>.02</b>
<b>ENG 1</b>	<b>8791.4</b>	<b>9226</b>	<b>18-Aug-2012</b>	<b>.03</b>
<b>ENG 2</b>	<b>7046.1</b>	<b>6912</b>	<b>18-Aug-2012</b>	<b>.03</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 500-32-54 32SL-54	LANDING GEAR - LANDING GEAR HANDLE LOCKING SOLENOID INSPECTION	YHU		RECOMMENDED	MTH 11-Apr-2006 HRS 17721		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SL 500-32-56 32SL-56	CLEVELAND SERVICE BULLETIN ESB7028 BRAKE ASSEMBLY BOLT REPLACEMENT	YHU		MANDATORY	MTH 11-Apr-2006 HRS 17721		A/R			N/A
<b>MOC : NOT APPLICABLE - NOT APPLICABLE</b>										
SL 500-32-57 R1 32SL-57 : REV1	LANDING GEAR - TEIJIN SEIKI MAIN AND NOSE LANDING GEAR ACTUATOR DOWN AND LOCKED SWITCH INSPECTION/ REPLACEMENT	YHU		RECOMMENDED	MTH 11-Apr-2006 HRS 17721		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SL 500-32-66 32SL-66	LANDING GEAR - NOSE LANDING GEAR WHEEL AND TIRE ASSEMBLY ATTACH HARDWARE INSPECTION / REPLACEMENT			RECOMMENDED	MTH 06-Oct-1994 HRS 13822		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SL 500-32-71 R1 32SL-71 : REV1	NOSE LANDING GEAR ICE PROTECTION BOOT INSTALLATION			OPTIONAL	MTH		A/R			
<b>MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME</b>										
SL 500-32-76 32SL-76	LANDING GEAR - EMERGENCY GEAR RELEASE INSPECTION	UNK		MANDATORY	MTH 08-Nov-2011 HRS 17973.7		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 500-33-03 33SB-3	LIGHTS - WING TIP RECOGNITION LIGHT INSTALLATION			OPTIONAL	MTH 15-Aug-1971		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 500-33-04 33SB-4	RUDDER MOUNTED OSCILLATING BEACON INSTALLATION			OPTIONAL	MTH 15-Aug-1971		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 500-33-08 R6 33SB-8 : REV6	LIGHTS - RUDDER MOUNTED OSCILLATING BEACON REPLACEMENT			OPTIONAL	MTH		A/R			
<b>MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME</b>										
SB 500-33-09 33SB-09	LIGHTS - LANDING LIGHT ELECTRICAL CIRCUIT MODIFICATION			OPTIONAL	MTH		A/R			
<b>MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME</b>										
SB 500-33-10 33SB-10	LIGHTS - EXIT SIGN REPLACEMENT			*CF OPTIONAL	MTH		A/R			
<b>MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME</b>										
SB 500-33-12 33SB-12	LIGHTS - LANDING LIGHT CIRCUIT SWITCH MODULE INSTALLATION			OPTIONAL	MTH		A/R			
<b>MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME</b>										
SB 500-33-13 R1 33SB-13 : REV1	LIGHTS - EMERGENCY LIGHTING BATTERY PACK UPGRADE			OPTIONAL	MTH		A/R			
<b>MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME</b>										
SB 500-33-14 33SB-14	LIGHTS - LED TAIL POSITION LIGHT INSTALLATION			OPTIONAL	MTH 09-May-2008 HRS 17851		A/R			Complete
<b>MOC : COMPLIED WITH</b>										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **JALAIR LP**  
 Aircraft Model: **501 - MODEL 501**  
 Aircraft Serial: **501-0169** Unit: **0566** Reg No: **C-GFEE**  
 Airworthiness: **31-Oct-1980**  
 Print Date: **22-Aug-2012 7:10PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>17995.4</b>	<b>22037</b>	<b>18-Aug-2012</b>	<b>.02</b>
<b>ENG 1</b>	<b>8791.4</b>	<b>9226</b>	<b>18-Aug-2012</b>	<b>.03</b>
<b>ENG 2</b>	<b>7046.1</b>	<b>6912</b>	<b>18-Aug-2012</b>	<b>.03</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 500-33-04 33SL-04	LIGHTS - LANDING LIGHT SWITCH INSPECTION/REPLACEMENT			MANDATORY	MTH 02-Dec-1993 HRS 13236		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 500-34-07 34SB-7	NAVIGATION - INSTALLATION OF COLLINS RADIO ALTIMETER			OPTIONAL	MTH		A/R			
<b>MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME</b>										
SB 500-34-15 34SB-15	9500 POUND ZERO FUEL WEIGHT INSTALLATION			OPTIONAL	MTH 15-Aug-1971		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 500-34-29 34SB-29	NAVIGATION - AREA NAVIGATION ADAPTER CABLE INSTALLATION			OPTIONAL	MTH		A/R			
<b>MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME</b>										
SB 500-34-31 34SB-31	NAVIGATION - INSTALLATION OF ANGLE-OF-ATTACK SYSTEM			OPTIONAL	MTH 15-Aug-1971		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 500-34-32 34SB-32	NAVIGATION - AREA NAV (RNS-3500) SYSTEM INSTALLATION			OPTIONAL	MTH		A/R			
<b>MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME</b>										
SB 500-34-40 34SB-40	NAVIGATION - MARKER BEACON LAMP DIMMING			OPTIONAL	MTH		A/R			
<b>MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME</b>										
SB 500-34-45 34SB-45	POINTER SENTRY ELT INSTALLATION			OPTIONAL	MTH		A/R			
<b>MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME</b>										
SB 500-34-49 34SB-49	NAVIGATION - VLF SYSTEM H-FIELD LOOP ANTENNA INSTALLATION			OPTIONAL	MTH		A/R			
<b>MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME</b>										
SB 500-34-50 34SB-50	NAVIGATION - DME/VLF AND VNAV WIRING MODIFICATION - REMOVE THE VALID DISTANCE/BEARING SIGNAL FROM VNAV WHEN IN VLF MODE	YHU		MANDATORY	MTH 11-Apr-2006 HRS 17721		A/R			N/A
<b>MOC : NOT APPLICABLE - NOT APPLICABLE</b>										
SB 500-34-51 34SB-51	NAVIGATION - FLIGHT DIRECTOR VOR/LOC ANGULAR INTERCEPT LOGIC IN VLF MODE INTERCONNECT WIRING MODIFICATION	YHU		RECOMMENDED	MTH 11-Apr-2006 HRS 17721		A/R			N/A
<b>MOC : NOT APPLICABLE - NOT APPLICABLE</b>										
SB 500-34-57 34SB-57	NAVIGATION - STARTER-GENERATOR AND GCU FILTER INSTALLATION	YHU		RECOMMENDED	MTH 11-Apr-2006 HRS 17721		A/R			N/A
<b>MOC : NOT APPLICABLE - NOT APPLICABLE</b>										
ASB 500-34-58 R1 34SBA58 : REV1	NAVIGATION - VG14A VERTICAL GYRO INSPECTION			MANDATORY	MTH 17-Nov-1989 HRS 10001		A/R			Complete
<b>MOC : COMPLIED WITH - NOT APPLICABLE</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **JALAIR LP**  
 Aircraft Model: **501 - MODEL 501**  
 Aircraft Serial: **501-0169** Unit: **0566** Reg No: **C-GFEE**  
 Airworthiness: **31-Oct-1980**  
 Print Date: **22-Aug-2012 7:10PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>17995.4</b>	<b>22037</b>	<b>18-Aug-2012</b>	<b>.02</b>
<b>ENG 1</b>	<b>8791.4</b>	<b>9226</b>	<b>18-Aug-2012</b>	<b>.03</b>
<b>ENG 2</b>	<b>7046.1</b>	<b>6912</b>	<b>18-Aug-2012</b>	<b>.03</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 500-34-59 R1 34SB-59 : REV1	NAVIGATION - VN-212 SIGNAL GROUND WIRING MODIFICATION			OPTIONAL	MTH		A/R			
	<b>MOC :</b> - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SB 500-34-64 34SB-64	NAVIGATION - HONEYWELL RADIO ALTIMETER MODEL RT-300 INSTALLATION			OPTIONAL	MTH		A/R			
	<b>MOC :</b> - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SB 500-34-65 34SB-65	NAVIGATION - REDUCED VERTICAL SEPARATION MINIMUM (RVSM) OPERATION MODIFICATION			OPTIONAL	MTH		A/R			
	<b>MOC :</b> - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SB 500-34-66 34SB-66	NAVIGATION - SANDEL TERRAIN AWARENESS WARNING SYSTEM (TAWs) INSTALLATION			OPTIONAL	MTH		A/R			
	<b>MOC :</b> - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SB 500-34-67 34SB-67	NAVIGATION - SIGMA-TEK CONTROL PANEL INSTALLATION			OPTIONAL	MTH		A/R			
	<b>MOC :</b> - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SL 500-34-23 34SL-23	GLOBAL NAVIGATION SB 00021 - MODIFICATION OF BATTERY CHARGING CARD P/N 11745-1			RECOMMENDED	MTH 21-Jun-2005 HRS 17697		A/R			N/A
	<b>MOC :</b> NOT APPLICABLE - NOT APPLICABLE									
SL 500-34-24 34SL-24	GLOBAL NAVIGATION SB 0002 - MODIFICATION OF OEU INTERFACE BRD, SWITCH SETTING	YHU		RECOMMENDED	MTH 11-Apr-2006 HRS 17721		A/R			N/A
	<b>MOC :</b> NOT APPLICABLE - NOT APPLICABLE									
SL 500-34-29 34SL-29	GLOBAL NAVIGATION SB0023 - MODIFICATION OF RCU FR WASH RECEP, SERIES 2, 2A, OR 2M SYSTEM			OPTIONAL	MTH		A/R			
	<b>MOC :</b> - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SL 500-34-32 34SL-32	FLIGHT DIRECTOR - BACK COURSE LIMITATION			RECOMMENDED	MTH HRS		100			
	OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
	<b>MOC :</b>									
SL 500-34-37 34SL-37	DORNE AND MARGOLIN DMN4-17-4 NAV ANTENNA COUPLER INSPECTION			RECOMMENDED	MTH		A/R			
	<b>MOC :</b> - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SB 500-35-04 R4	OXYGEN - INSTALLATION OF 64 CUBIC FOOT OXYGEN SYSTEM			OPTIONAL			-			
	<b>MOC :</b>									
SB 500-35-04 35SB-4	OXYGEN - INSTALLATION OF 64 CUBIC FOOT OXYGEN SYSTEM			OPTIONAL	MTH 15-Aug-1971		A/R			Complete
	<b>MOC :</b> COMPLIED WITH									
SB 500-35-06 R1 35SB-06 : REV1	OXYGEN - EROS OXYGEN MASK INSTALLATION			OPTIONAL	MTH		A/R			
	<b>MOC :</b> - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									



# CESCOM 10 - Aircraft Status Report

Owner: **JALAIR LP**  
 Aircraft Model: **501 - MODEL 501**  
 Aircraft Serial: **501-0169** Unit: **0566** Reg No: **C-GFEE**  
 Airworthiness: **31-Oct-1980**  
 Print Date: **22-Aug-2012 7:10PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>17995.4</b>	<b>22037</b>	<b>18-Aug-2012</b>	<b>.02</b>
<b>ENG 1</b>	<b>8791.4</b>	<b>9226</b>	<b>18-Aug-2012</b>	<b>.03</b>
<b>ENG 2</b>	<b>7046.1</b>	<b>6912</b>	<b>18-Aug-2012</b>	<b>.03</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 500-35-06 35SB-06	OXYGEN - EROS OXYGEN MASK INSTALLATION OPTIONAL				MTH		A/R			
<b>MOC :</b> - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SL 500-35-06	OXYGEN - OXYGEN BOTTLE INSPECTION INFORMATIONAL				MTH		A/R			
<b>MOC :</b>										
SB 500-36-04 36SB-04	PNEUMATIC - ENGINE BLEED AIR CONNECTOR IMPROVEMENT OPTIONAL				MTH		A/R			
<b>MOC :</b> - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB 500-36-05 R1 36SB-05 : REV1	PNEUMATIC - DOOR SEAL VALVE REPLACEMENT OPTIONAL				MTH		A/R			
<b>MOC :</b> - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB 500-52-14 52SB-14	CBN DOOR STEP HINGE SUPERSEDED				MTH HRS		100			
SERVICE BULLETIN/LETTER CANCELLED OR SUPERSEDED										
<b>MOC :</b>										
SB 500-52-15 52SB-15	DOORS - CABIN DOOR HINGE PIN AND NEEDLE BEARING REPLACEMENT AND LUBE FITTING INSTALLATION OPTIONAL				MTH		A/R			
<b>MOC :</b> - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB 500-52-16 52SB-16	DOORS - ENTRY STEP ASSEMBLY IMPROVEMENT RECOMMENDED				MTH 17-Jan-1987 HRS 7270		A/R			Complete
<b>MOC :</b> COMPLIED WITH										
SB 500-52-18 52SB-18	DOOR - BAGGAGE DOOR POSITIVE SAFETY LOCK INSTALLATION RECOMMENDED				MTH HRS		150			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
<b>MOC :</b>										
SB 500-52-19 52SB-19	DOORS - ENTRY DOOR STEP CATCH COVER INSTALLATION (WITH STANDARD DOOR AND STEP) YHU				MTH 11-Apr-2006 HRS 17721		A/R			N/A
<b>MOC :</b> NOT APPLICABLE - NOT APPLICABLE										
ASL 500-52-04	DOORS - EMERGENCY EXIT INSPECTION UNK				DAYS 18-Jan-2012 HRS 17978.8		A/R			Complete
<b>MOC :</b> COMPLIED WITH - THE WORK DESCRIBED ABOVE HAS BEEN PERFORMED IN ACCORDANCE WITH THE APPLICABLE STANDARDS OF AIRWORTHINESS.										
SB 500-53-03 53SB-3	FUSELAGE - DRAG CHUTE INSTALLATION OPTIONAL				MTH		A/R			
<b>MOC :</b> - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB 500-53-13 53SB-13	FUSELAGE - TAILCONE SKIN - INSPECTION AND MODIFICATION OF VERTICAL FIN SPAR INTERFERENCE YTS				MTH 24-Mar-1984 HRS 3504		A/R			Complete
<b>MOC :</b> COMPLIED WITH										
SB 500-53-14 53SB-14	NOSE DRIP CAP INSTALLATION OPTIONAL				MTH		A/R			
<b>MOC :</b> - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB 500-53-20 53SB-20	FUSELAGE - FLIGHT CREW SEAT RAIL AND BEAM RIVETS INSPECTION/INSTALLATION RECOMMENDED				MTH 15-Aug-1995 HRS 14446		A/R			Complete
<b>MOC :</b> COMPLIED WITH										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.





# CESCOM 10 - Aircraft Status Report

Owner: **JALAIR LP**  
 Aircraft Model: **501 - MODEL 501**  
 Aircraft Serial: **501-0169** Unit: **0566** Reg No: **C-GFEE**  
 Airworthiness: **31-Oct-1980**  
 Print Date: **22-Aug-2012 7:10PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>17995.4</b>	<b>22037</b>	<b>18-Aug-2012</b>	<b>.02</b>
<b>ENG 1</b>	<b>8791.4</b>	<b>9226</b>	<b>18-Aug-2012</b>	<b>.03</b>
<b>ENG 2</b>	<b>7046.1</b>	<b>6912</b>	<b>18-Aug-2012</b>	<b>.03</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 500-53-22 53SB-22	FUSLEAGE - DORSAL FIN INSTALLATION AND MATERIAL IMPROVEMENT			OPTIONAL	MTH		A/R			
<b>MOC :</b> - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB 500-53-23 53SB-23	AN3-5A BOLT INSPECTION/REPLACEMENT	YHU		RECOMMENDED	MTH 11-Apr-2006 HRS 17721		-			N/A
<b>MOC :</b> NOT APPLICABLE - NOT APPLICABLE										
SB 500-53-26 53SB-26	FUSELAGE - WHEEL WELL BOX IMPROVEMENT			OPTIONAL	MTH		A/R			
<b>MOC :</b> - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SL 500-53-01 53SL-1	NOSE BAGGAGE AND TAILCONE ACCESS DOOR LATCHES	TOL		MANDATORY	MTH 13-Nov-1981 HRS 345		A/R			Complete
<b>MOC :</b> COMPLIED WITH										
SL 500-53-02 53SL-2	TAILCONE SKIN INTERFERENCE WITH VERTICAL FIN SPAR INSPECTION	YTS		MANDATORY	MTH 11-Feb-1983 HRS 1815		A/R			Complete
<b>MOC :</b> COMPLIED WITH										
SL 500-53-05 53SL-05	FUSELAGE - INTERCOSTAL DRAINAGE PATH INSPECTION	YHU		RECOMMENDED	MTH 11-Apr-2006 HRS 17721		A/R			Complete
<b>MOC :</b> COMPLIED WITH										
SB 500-55-04 55SB-4	STABILIZERS - VERTICAL FIN FORWARD SPAR MODIFICATION			MANDATORY	MTH HRS		1			
MANDATORY IF WEAR EXCEEDS ACCEPTABLE LIMITS PRESENTED IN SERVICE BULLETIN SB53-13 OR SB550-53-6										
<b>MOC :</b>										
SL 500-55-01 55SL-01	STABILIZERS - RUDDER TORQUE TUBE INTERNAL CORROSION INSPECTION			RECOMMENDED	MTH 15-Mar-1990 HRS 10265		A/R			Complete
<b>MOC :</b> COMPLIED WITH - INTENT ACCOMPLISHED DURING PREVIOUS MAINTENANCE OR THROUGH ALTERNATE METHOD OF COMPLIANCE.										
SL 500-57-04 57SL-04	WIRE BUNDLE ROUTING IMPROVEMENT	YHU		RECOMMENDED	MTH 11-Apr-2006 HRS 17721		A/R			Complete
<b>MOC :</b> COMPLIED WITH										
SL 500-57-05 57SL-5	WING CARRY THRU SPAR FITTING INSPECTION			INFORMATIONAL	MTH 09-Mar-1995 HRS 14118		-			Complete
<b>MOC :</b> COMPLIED WITH										
SL 500-71-07 71SL-7	ENGINE WIRE BUNDLE INSPECTION	YTS		RECOMMENDED	MTH 06-Mar-1983 HRS 1908		A/R			Complete
<b>MOC :</b> COMPLIED WITH										
SL 500-71-09 71SL-9	ENGINE BLEED AIR LINE RETAINER INSPECTION	YTS		RECOMMENDED	MTH 14-Jul-1982 HRS 994		A/R			Complete
<b>MOC :</b> COMPLIED WITH										
SL 500-72-03 72SL-3	ENGINE - JT15D FAN BLADE INSPECTION	YHU			MTH 11-Apr-2006 HRS 17721		A/R			Complete
<b>MOC :</b> COMPLIED WITH - INTENT ACCOMPLISHED DURING PREVIOUS MAINTENANCE OR THROUGH ALTERNATE METHOD OF COMPLIANCE.										
SL 500-72-04 72SL-04	ENGINE - INTRODUCTION OF NEW IMPROVED GAS GENERATOR CASE			RECOMMENDED	MTH HRS		150			
P&WC SB 7286 REV2 RECOMMENDS ACCOMPLISHMENT AT ENGINE OVERHAUL AFTER 5-04-90.										
<b>MOC :</b>										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **JALAIR LP**  
 Aircraft Model: **501 - MODEL 501**  
 Aircraft Serial: **501-0169** Unit: **0566** Reg No: **C-GFEE**  
 Airworthiness: **31-Oct-1980**  
 Print Date: **22-Aug-2012 7:10PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>17995.4</b>	<b>22037</b>	<b>18-Aug-2012</b>	<b>.02</b>
<b>ENG 1</b>	<b>8791.4</b>	<b>9226</b>	<b>18-Aug-2012</b>	<b>.03</b>
<b>ENG 2</b>	<b>7046.1</b>	<b>6912</b>	<b>18-Aug-2012</b>	<b>.03</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 500-72-10  LEFT ENGINE <i>72SL-10 : E1**L</i>	ENGINE - TRANSMITTAL OF PRATT & WHITNEY CANADA (P&WC) SERVICE BULLETIN JT15D-72-7590, TURBOFAN ENGINE BORESCOPE INSPECTION OF IMPELLER REAR FACE AND COMMERCIAL SUPPORT PROGRAM NOTIFICATION (CSPN) C03001R1	YHU		RECOMMENDED	MTH 11-Apr-2006 HRS 17721		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SL 500-72-10  RIGHT ENGINE <i>72SL-10 : E2**R</i>	TRANSMITTAL OF PRATT & WHITNEY CANADA (P&WC) SERVICE BULLETIN JT15D-72-7590, TURBOFAN ENGINE BORESCOPE INSPECTION OF IMPELLER REAR FACE AND COMMERCIAL SUPPORT PROGRAM NOTIFICATION (CSPN) C03001R1	YHU		RECOMMENDED	MTH 11-Apr-2006 HRS 17721		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 72-7003 R35 E1	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY			RECOMMENDED			-			
<b>MOC :</b>										
SB 72-7459 R1 E1	REPLACEMENT OF IGNITER			OPTIONAL			A/R			
<b>MOC :</b>										
SB 72-7459 R2 E1	REPLACEMENT OF IGNITER			OPTIONAL			-			
<b>MOC :</b>										
SB 72-7459 R2 E2	REPLACEMENT OF IGNITER			OPTIONAL			-			
<b>MOC :</b>										
SB 72-7589 R1 E1	HIGH TURBINE DISC BALANCING ASSEMBLY - REPLACEMENT OF			OPTIONAL			-			
<b>MOC :</b>										
SB 72-7589 R1 E2	HIGH TURBINE DISC BALANCING ASSEMBLY - REPLACEMENT OF			OPTIONAL			-			
<b>MOC :</b>										
SB 72-7625 R1 E1	REPLACEMENT OF GASKET			RECOMMENDED			A/R			
<b>MOC :</b>										
SB 72-7627 E1	LOW PRESSURE TURBINE INTERSTAGE ROTOR AIR SEAL AND ROTOR AIR SEAL - REPLACEMENT OF			RECOMMENDED			-			
<b>MOC :</b>										
SB 72-7627 E2	LOW PRESSURE TURBINE INTERSTAGE ROTOR AIR SEAL AND ROTOR AIR SEAL - REPLACEMENT OF			RECOMMENDED			-			
<b>MOC :</b>										
SB 500-74-01 <i>74SB-1</i>	IGNITION - DUAL IGNITION EXCITER BOX INSTALLATION			OPTIONAL	MTH		A/R			
<b>MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME</b>										
SL 500-74-02 <i>74SL-2</i>	IMPROVED ENGINE EXCITER BOX	YTS		RECOMMENDED	MTH 02-Feb-1984 HRS 3283		A/R			Complete
<b>MOC : COMPLIED WITH</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **JALAIR LP**  
 Aircraft Model: **501 - MODEL 501**  
 Aircraft Serial: **501-0169** Unit: **0566** Reg No: **C-GFEE**  
 Airworthiness: **31-Oct-1980**  
 Print Date: **22-Aug-2012 7:10PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>17995.4</b>	<b>22037</b>	<b>18-Aug-2012</b>	<b>.02</b>
<b>ENG 1</b>	<b>8791.4</b>	<b>9226</b>	<b>18-Aug-2012</b>	<b>.03</b>
<b>ENG 2</b>	<b>7046.1</b>	<b>6912</b>	<b>18-Aug-2012</b>	<b>.03</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 500-74-04 <i>74SL-04</i>	IGNITION - TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN 7567R1 TURBOFAN ENGINE IGNITER BOX GROUNDING STRAP - INTRODUCTION OF			RECOMMENDED	MTH 23-Oct-2001 HRS 17182		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 500-77-02 <i>77SB-2</i>	VERTICAL SCALE INSTRUMENTS SEPARATION			OPTIONAL	MTH		A/R			
<b>MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME</b>										
SB 500-78-01 <i>78SB-1</i>	EXHAUST - THRUST REVERSER INSTALLATION			OPTIONAL	MTH 15-Aug-1971		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 500-78-11 <i>78SB-11</i>	EXHAUST - THRUST REVERSER THROTTLE LOAD LIMITER MODIFICATION			RECOMMENDED	MTH 10-May-1993 HRS 12835		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 500-78-12 <i>78SB-12 : 500</i>	EXHAUST - THRUST REVERSER THROTTLE STOP SOLENOID GROUND IMPROVEMENT			OPTIONAL	MTH		A/R			
<b>MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME</b>										
SL 500-78-10 LEFT ENGINE <i>78SL-10</i>	THRUST REVERSER DOOR BUMPER PAD INSTALLATION	YTS		OPTIONAL	MTH 18-May-1982 HRS 792		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SL 500-78-10 RIGHT ENGINE <i>78SL-10</i>	THRUST REVERSER DOOR BUMPER PAD INSTALLATION	YTS		OPTIONAL	MTH 18-May-1982 HRS 792		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SL 500-78-11 LEFT ENGINE <i>78SL-11</i>	THRUST REVERSER INBOARD STANG MODIFICATION	YTS		OPTIONAL	MTH 08-Apr-1982 HRS 698		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SL 500-78-11 RIGHT ENGINE <i>78SL-11</i>	THRUST REVERSER INBOARD STANG MODIFICATION	YTS		OPTIONAL	MTH 08-Apr-1982 HRS 698		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SL 500-78-12 <i>78SL-12</i>	THRUST REVERSER JUNCTION BOX MODIFICATION	YHU		RECOMMENDED	MTH 11-Apr-2006 HRS 17721		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SL 500-78-13 <i>78SL-13</i>	THRUST REVERSER SYSTEM OPERATIONAL TEST			RECOMMENDED	MTH 17-Aug-1990 HRS 10578		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SL 500-78-16 <i>78SL-16</i>	EXHAUST - THRUST REVERSER STANG FAIRING SUPPORT FORMER REPLACEMENT (ROHR INC. SERVICE BULLETIN NO. CIT 78-11)			RECOMMENDED	MTH 06-Apr-1994 HRS 13432		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
SB 500-80-05 <i>80SB-05</i>	STARTING - REPLACEMENT OF SUPPRESSION DIODE WITH TRANZORB			OPTIONAL	MTH		A/R			
<b>MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME</b>										



# CESCOM 10 - Aircraft Status Report

Owner: **JALAIR LP**  
 Aircraft Model: **501 - MODEL 501**  
 Aircraft Serial: **501-0169** Unit: **0566** Reg No: **C-GFEE**  
 Airworthiness: **31-Oct-1980**  
 Print Date: **22-Aug-2012 7:10PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>17995.4</b>	<b>22037</b>	<b>18-Aug-2012</b>	<b>.02</b>
<b>ENG 1</b>	<b>8791.4</b>	<b>9226</b>	<b>18-Aug-2012</b>	<b>.03</b>
<b>ENG 2</b>	<b>7046.1</b>	<b>6912</b>	<b>18-Aug-2012</b>	<b>.03</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 500-99-12	MISCELLANEOUS - CESSNA PART NUMBER SUFFIXES FOR REMANUFACTURED PARTS			INFORMATIONAL			A/R			
	<b>MOC :</b>									
SL 500-99-13	MISCELLANEOUS - CESSNA SERVICE DOCUMENT CHANGE NOTIFICATION			INFORMATIONAL			A/R			
	<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **JALAIR LP**  
 Aircraft Model: **501 - MODEL 501**  
 Aircraft Serial: **501-0169** Unit: **0566** Reg No: **C-GFEE**  
 Airworthiness: **31-Oct-1980**  
 Print Date: **22-Aug-2012 7:10PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>17995.4</b>	<b>22037</b>	<b>18-Aug-2012</b>	<b>.02</b>
<b>ENG 1</b>	<b>8791.4</b>	<b>9226</b>	<b>18-Aug-2012</b>	<b>.03</b>
<b>ENG 2</b>	<b>7046.1</b>	<b>6912</b>	<b>18-Aug-2012</b>	<b>.03</b>

## Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
AD 1998-04-38 <i>30AD-02</i>	TO MINIMIZE THE POTENTIAL HAZARDS ASSOCIATED WITH OPERATING THE AIRPLANE IN SEVERE ICING CONDITIONS BY PROVIDING MORE CLEARLY DEFINED PROCEDURES AND LIMITATIONS ASSOCIATED WITH SUCH CONDITIONS			MANDATORY	MTH 27-Apr-1998 HRS 15869		-			Complete
<b>MOC : COMPLIED WITH</b>										
AD 2001-23-17 <i>34AD-26</i>	GNS 430 UNITS, PART NUMBER 011-00280-00; REFER TO AD FOR SERIAL NUMBER EFFECTIVITY.			MANDATORY	MTH 01-Feb-2002 HRS 17268		-			Complete
<b>MOC : COMPLIED WITH - NOT APPLICABLE</b>										
AD 2006-04-10 <i>26AD-02</i>	THIS AD REQUIRES INSTALLING IDENTIFICATION SLEEVES ON THE WIRES FOR THE POSITIVE AND NEGATIVE STUDS OF THE ENGINE AND/ OR (APU) FIRE EXTINGUISHING BOTTLES, AS APPLICABLE, AND RECONNECTING THE WIRES TO THE CORRECT TERMINAL STUDS.				MTH 11-Apr-2006 HRS 17720		-			Complete
<b>MOC : COMPLIED WITH</b>										
AD 1990-07-10 R1 <i>21AD-01</i>	FREON AIR CONDITIONERS INSTALLED IN THE AFT SECTION OF THE BAGGAGE COMPARTMENT.			MANDATORY	MTH 21-Apr-1990 HRS 10367		-			Complete
<b>MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED</b>										
AD 1995-25-10 <i>21AD-02</i>	REPLACE THE OUTFLOW SAFETY VALVE IN ACCORDANCE WITH ALLIED SIGNAL SERVICE BULLETIN 103576-21-4056.			MANDATORY	MTH 15-Aug-1995 HRS 14446		-			Complete
<b>MOC : COMPLIED WITH</b>										
AD 1983-01-06 <i>25AD-1</i>	TO DETECT LIFE PRESERVERS AND FLOTATION DEVICES WHICH HAVE CO2 INFLATION VALVE MANIFOLDS THAT MAY OPERATE IMPROPERLY, AND TO CORRECT THE DEFICIENCY, PERFORM THE FOLLOWING IN ACCORDANCE WITH THE ACCOMPLISHMENT INSTRUCTIONS, PARAGRAPH 2, OF SWITLIK PARACHUTE COMPANY, INC., SERVICE BULLETIN 25-00-16, DATED APRIL 1, 1982:				MTH HRS		1000			
NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
<b>MOC :</b>										
AD 1989-06-01 <i>25AD-02</i>	PREVENT THE IMPROPER FUNCTIONING OF THE CARBON DIOXIDE (CO2) INFLATORS ON TSO-C13, LIFE PRESERVERS AND TSO-C72 INDIVIDUAL FLOTATION DEVICES			MANDATORY	MTH 08-May-1989 HRS 9549		-			Complete
<b>MOC : COMPLIED WITH - NOT APPLICABLE BY DATE OF MANUFACTURE</b>										
AD 1998-25-10 <i>25AD-03</i>	SEAT RESTRAINT SYSTEM			MANDATORY	MTH 20-Mar-2000 HRS 16657		A/R			Complete
<b>MOC : COMPLIED WITH - NOT APPLICABLE</b>										
AD 2007-11-17 <i>26AD-03</i>	IDENTIFY WIRES FOR FIRE EXTINGUISHING BOTTLES			MANDATORY	MTH 05-Jul-2007 HRS 17787		A/R			Complete
<b>MOC : COMPLIED WITH</b>										
AD 2010-04-16 (G) <i>26AD-06</i>	REPLACE TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS MANUFACTURED BY SICLI WITH SERVICABLE UNIT	MTL		MANDATORY	DAYS 27-Sep-2011 HRS 17973.7 LDG 22008		A/R			N/A
<b>MOC : NOT APPLICABLE - NOT APPLICABLE - FIRE EXTINGUISHERS ARE ABC TYPE</b>										



## CESCOM 10 - Aircraft Status Report

Owner: **JALAIR LP**  
 Aircraft Model: **501 - MODEL 501**  
 Aircraft Serial: **501-0169** Unit: **0566** Reg No: **C-GFEE**  
 Airworthiness: **31-Oct-1980**  
 Print Date: **22-Aug-2012 7:10PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>17995.4</b>	<b>22037</b>	<b>18-Aug-2012</b>	<b>.02</b>
<b>ENG 1</b>	<b>8791.4</b>	<b>9226</b>	<b>18-Aug-2012</b>	<b>.03</b>
<b>ENG 2</b>	<b>7046.1</b>	<b>6912</b>	<b>18-Aug-2012</b>	<b>.03</b>

### Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
AD 2010-04-16	TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS MANUFACTURED BY SICLI			MANDATORY			A/R			
<b>MOC :</b>										
AD 2006-06-03 28AD-01	PREVENT FUEL VAPOR IGNITION			MANDATORY	MTH 11-Apr-2006 HRS 17720		-			Complete
<b>MOC : COMPLIED WITH</b>										
AD 1998-25-02	TO PREVENT THE DISPLAY OF TARGET INDICATORS ON THE WRONG SIDE OF THE AIRCRAFT CAUSED BY AN INTERNAL COMPONENT FAILURE IN THE SKY497 INSTALLATIONS WITH A TOP-MOUNTED ANTENNA, WHICH COULD RESULT IN THE PILOT MAKING AN INCORRECT INITIAL MANEUVER BASED ON THE DISPLAYED INFORMATION WHILE TRYING TO VISUALLY ACQUIRE THE AIRCRAFT.			MANDATORY	MTH 21-Jun-2005 HRS 17697		-			N/A
<b>MOC : NOT APPLICABLE - NOT APPLICABLE-EQUIPMENT NOT INSTALLED</b>										
AD 2003-13-08 34AD-27	GOODRICH AVIONICS SYSTEMS, INC. TAWS8000 TERRAIN AWARENESS WARNING SYSTEM			MANDATORY	MTH 21-Jun-2005 HRS 17697		-			N/A
<b>MOC : NOT APPLICABLE - NOT APPLICABLE-EQUIPMENT NOT INSTALLED</b>										
AD 2006-16-18 34AD-35	PREVENT A BEARING ERROR			SUPERSEDED	MTH 17-Oct-2006 HRS 17747		-			N/A
<b>MOC : NOT APPLICABLE - NOT APPLICABLE-EQUIPMENT NOT INSTALLED</b>										
AD 1994-19-06	TO PREVENT THE FLIGHT CREW FROM EXPERIENCING DIFFICULTY IN EXHALING INTO THE AFFECTED CREW OXYGEN MASKS.			MANDATORY	MTH 30-Jun-1997 HRS 15654		-			Complete
<b>MOC : COMPLIED WITH - NOT APPLICABLE BY COMPONENT PART NUMBER.</b>										
AD 1999-08-21 35AD-02	PREVENT REDUCED OXYGEN CONSUMPTION WHEN PASSENGERS ARE REQUIRED TO USE DEFECTIVE OXYGEN MASKS			MANDATORY	MTH 19-Nov-1999 HRS 16520		-			Complete
<b>MOC : COMPLIED WITH</b>										
AD 72-1	JT15D FAN BLADE INSP				MTH 11-Apr-2006 HRS 17720		-			Complete
<b>MOC : COMPLIED WITH</b>										
AD 1993-18-08 E1	PREVENT A HIGH PRESSURE TURBINE (HPT) ASSEMBLY FAILURE. AMENDMENT 39-8693			MANDATORY	MTH 01-Nov-1993 HRS 13172		-			Complete
<b>MOC : COMPLIED WITH</b>										
AD 2004-04-09 E1	TO PREVENT UNCONTAINED FAILURE OF THE IMPELLER AND POSSIBLE DAMAGE TO THE AIRPLANE	YHU		MANDATORY	MTH 11-Apr-2006 HRS 17720 LDG 21747		-			N/A
<b>MOC : NOT APPLICABLE - NOT APPLICABLE</b>										
AD 1993-05-15 78AD-01	TO PREVENT SEVERELY REDUCED CONTROLLABILITY OF ENGINE POWER AUTHORITY.			MANDATORY	MTH 10-May-1993 HRS 12835			A/R		Complete
<b>MOC : COMPLIED WITH</b>										
AD 2004-08-15 34AD-28	PREVENT THE LOADING OF THE BARO SET POTENTIOMETER, WHICH COULD RESULT IN AN UNACCEPTABLE ALTITUDE ERROR.				MTH 21-Jun-2005 HRS 17697			A/R		N/A
<b>MOC : NOT APPLICABLE - NOT APPLICABLE-EQUIPMENT NOT INSTALLED</b>										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **JALAIR LP**  
 Aircraft Model: **501 - MODEL 501**  
 Aircraft Serial: **501-0169** Unit: **0566** Reg No: **C-GFEE**  
 Airworthiness: **31-Oct-1980**  
 Print Date: **22-Aug-2012 7:10PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>17995.4</b>	<b>22037</b>	<b>18-Aug-2012</b>	<b>.02</b>
<b>ENG 1</b>	<b>8791.4</b>	<b>9226</b>	<b>18-Aug-2012</b>	<b>.03</b>
<b>ENG 2</b>	<b>7046.1</b>	<b>6912</b>	<b>18-Aug-2012</b>	<b>.03</b>

## Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
AD 2004-09-05 <i>32AD-01</i>	PREVENT JAMMING OF THE WHEEL/TIRE ASSEMBLY	YHU			MTH 11-Apr-2006 HRS 17720 LDG 21747		-			N/A

**MOC : NOT APPLICABLE - NOT APPLICABLE**



## CESCOM 10 - Aircraft Status Report

Owner: **JALAIR LP**  
 Aircraft Model: **501 - MODEL 501**  
 Aircraft Serial: **501-0169** Unit: **0566** Reg No: **C-GFEE**  
 Airworthiness: **31-Oct-1980**  
 Print Date: **22-Aug-2012 7:10PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>17995.4</b>	<b>22037</b>	<b>18-Aug-2012</b>	<b>.02</b>
<b>ENG 1</b>	<b>8791.4</b>	<b>9226</b>	<b>18-Aug-2012</b>	<b>.03</b>
<b>ENG 2</b>	<b>7046.1</b>	<b>6912</b>	<b>18-Aug-2012</b>	<b>.03</b>

### Factory Installed

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
00FO-04D <i>00FO-04 : D</i>	FOREIGN CERT-GERMAN FACTORY OPTION	*CF		192D FO	MTH 31-Oct-1980		-			
21FO-05A <i>21FO-05 : A</i>	RH FAN INSTALLATION FORWARD DIVIDER FACTORY OPTION	*CF		180A FO	MTH 31-Oct-1980		-			
23FO-01C <i>23FO-01 : C</i>	HF COM SYSTEM COLLIN HF-200 W/ADF 2 FACTORY OPTION	*CF		631C FO	MTH 31-Oct-1980		-			
23FO-02	25 KHZ COM TRANSCVR P/N 622-1879-001 FACTORY OPTION	*CF		632 FO	MTH 31-Oct-1980		-			
24FO-01B <i>24FO-01 : B</i>	BATTERY & MONITOR FOR 20 CELL FACTORY OPTION	*CF		12B FO	MTH 31-Oct-1980		-			
24FO-02C <i>24FO-02 : C</i>	INVERTER 600 VA DUAL EXH FWD SGL FLT DIR FACTORY OPTION	*CF		26C FO	MTH 31-Oct-1980		-			
25FO-04	MAP CASE FACTORY OPTION	*CF		103 FO	MTH 31-Oct-1980		-			
25FO-07	SEATING OPT STANDARD FACTORY OPTION	*CF		109 FO	MTH 31-Oct-1980		-			
25FO-18D <i>25FO-18 : D</i>	JUMP SEAT-AFT BAGGAGE COMPARTMENT FACTORY OPTION	*CF		121D FO	MTH 31-Oct-1980		-			
25FO-20G <i>25FO-20 : G</i>	EXECUTIVE TABLE USED W/STD & OPT A FACTORY OPTION	*CF		124G FO	MTH 31-Oct-1980		-			
25FO-37	CHIMES UNIT FACTORY OPTION	*CF		166 FO	MTH 31-Oct-1980		-			
25FO-38	AFT FOLDING DOOR FACTORY OPTION	*CF		184 FO	MTH 31-Oct-1980		-			
25FO-39A <i>25FO-39 : A</i>	INTRCHNGE KIT-LOUNGE SEAT & STANDARD BAR FACTORY OPTION	*CF		196A FO	MTH 31-Oct-1980		-			
31FO-01C <i>31FO-01 : C</i>	CLOCK 24 HR 8 DAY RH FACTORY OPTION	*CF		23C FO	MTH 31-Oct-1980		-			
31FO-02B <i>31FO-02 : B</i>	CLOCK DIGITAL ELECTRIC 24 HOUR LH FACTORY OPTION	*CF		182B FO	MTH 31-Oct-1980		-			
32FO-02	BRAKES EXTENDED LIFE FACTORY OPTION	*CF		93 FO	MTH 31-Oct-1980		-			
33FO-02B <i>33FO-02 : B</i>	LIGHT-RECOGNITION WING-TIP MOUNTED FACTORY OPTION	*CF		49B FO	MTH 31-Oct-1980		-			
33FO-03D <i>33FO-03 : D</i>	LIGHT-ROTATE BEACON & VERT TAIL FLOODLHT FACTORY OPTION	*CF		51D FO	MTH 31-Oct-1980		-			





# CESCOM 10 - Aircraft Status Report

Owner: **JALAIR LP**  
 Aircraft Model: **501 - MODEL 501**  
 Aircraft Serial: **501-0169** Unit: **0566** Reg No: **C-GFEE**  
 Airworthiness: **31-Oct-1980**  
 Print Date: **22-Aug-2012 7:10PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>17995.4</b>	<b>22037</b>	<b>18-Aug-2012</b>	<b>.02</b>
<b>ENG 1</b>	<b>8791.4</b>	<b>9226</b>	<b>18-Aug-2012</b>	<b>.03</b>
<b>ENG 2</b>	<b>7046.1</b>	<b>6912</b>	<b>18-Aug-2012</b>	<b>.03</b>

## Factory Installed

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
34FO-02	INDICATOR-ANGLE OF ATTACK FACTORY OPTION				MTH 31-Oct-1980					
		*CF		11 FO						
34FO-03	HORIZON GYRO ELECTRIC STANDBY FACTORY OPTION				MTH 31-Oct-1980					
		*CF		142 FO						
34FO-06A 34FO-06 : A	9500 LB ZERO FUEL WT W/SURFACE DE-ICE FACTORY OPTION				MTH 31-Oct-1980					
		*CF		185A FO						
34FO-07D 34FO-07 : D	2ND TRANSPONDER-COLLINS TDR-90 FACTORY OPTION				MTH 31-Oct-1980					
		*CF		623D FO						
34FO-08	ALT REPORT DUAL WITH IDC ENCOD ALTIMETER FACTORY OPTION				MTH 31-Oct-1980					
		*CF		625 FO						
34FO-09L 34FO-09 : L	RADAR RDR-1100 EXCH FACTORY OPTION				MTH 31-Oct-1980					
		*CF		628L FO						
34FO-12P 34FO-12 : P	2ND ADF COLLINS ADF 60 W/HF COMM FWD FACTORY OPTION				MTH 31-Oct-1980					
		*CF		658P FO						
34FO-14	AA215 RAD ALTIMETER W/SEPARATE INDICATOR FACTORY OPTION				MTH 31-Oct-1980					
		*CF		672 FO						
34FO-15B 34FO-15 : B	FLIGHT DIRECTOR LH-5" SINGLE CUE SPERRY FACTORY OPTION				MTH 31-Oct-1980					
		*CF		679B FO						
34FO-20E 34FO-20 : E	VLF NAVIGATION SYSTEM GNS500A W/5" FDI FACTORY OPTION				MTH 31-Oct-1980					
		*CF		693E FO						
35FO-02B 35FO-02 : B	OXYGEN SYSTEM-64 CUBIC FEET FACTORY OPTION				MTH 31-Oct-1980					
		*CF		66B FO						
73FO-01C 73FO-01 : C	ENGINE SYNCHRONIZING INSTRUMENT W/TH REV FACTORY OPTION				MTH 31-Oct-1980					
		*CF		76C FO						
78FO-01	THRUST REVERSERS FACTORY OPTION				MTH 31-Oct-1980					
		*CF		193 FO						